

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
9	2211	1700577.711	1147857.066	Shell Rot		☐
11	2212	1700353.076	1147694.637	Shell Rot		☐
22	23197	1701504.919	1148084.623	Woodpecker Damage		☐
91	23241	1697410.394	1145270.284	Shell Rot		☐
130	3798	1697798.612	1149539.48	Internal Decay		☐
132	23795	1697545.055	1149532.146	Shell Rot		☐

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
159	17603	1698731.53	1148014.246	Internal Decay	#6 Duplex	☐
170	23770	1698369.726	1147973.078	Shell Rot	TRANS LOC # MISSING	☐
171	23769	1698287.841	1147984.137	Internal Decay		☐
200	1744	1699032.848	1148308.6	Shell Rot	2 STREET LIGHTS	☐
212	17617	1698250.298	1149197.349	Shell Rot		☐
213	23789	1697783.956	1149254.866	Shell Rot		☐
229	1230	1698294.311	1148315.403	Internal Decay		☐
230	1231	1698240.447	1148228.808	Heart Rot	CWL & MEDIACOM FIBER	☐
252	23738	1697641.472	1148438.392	Dry Rot		☐
267	23720	1697140.555	1148093.359	Top Rotten		☐
268	23719	1697147.492	1148122.763	Heart Rot		☐
276	17654	1697149.842	1148313.751	Shell Rot		☐
284	17647	1697008.891	1148770.378	Internal Decay	TRANSFORMER LOC # FADED	☐
304	23712	1697290.557	1147578.399	Heart Rot		☐
328	17660	1696249.342	1149006.105	Shell Rot		☐
338	1254	1696607.397	1149286.006	Internal Decay	CWL & CENTURY LINK FIBER	☐
349	17663	1695943.505	1149181.95	Shell Rot		☐
356	17674	1696634.394	1150603.96	Shell Rot		☐
391	21866	1694923.912	1150421.965	Shell Rot	CWL & CENTURY LINK FIBER	☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 1 of 2

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
392	21865	1695123.481	1150419.662	Internal Decay	CWL & CENTURY LINK FIBER	☐
393	21864	1695335.805	1150413.263	Shell Rot	CWL & CENTURY LINK FIBER	☐
395	21862	1695694.05	1150412.06	Internal Decay	CWL & CENTURY LINK FIBER	☐
396	21861	1695877.582	1150409.802	Shell Rot	CWL & CENTURY LINK FIBER	☐
398	17672	1696276.374	1150401.36	Internal Decay	CWL & CENTURY LINK FIBER	☐
410	21661	1694639.885	1147765.49	Heart Rot		☐
411	21652	1694439.564	1147757.227	Internal Decay		☐
420	21660	1693363.487	1147586.438	Shell Rot		☐

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
424	23698	1696316.813	1147530.035	Internal Decay		☐
425	23699	1696315.599	1147643.21	Shell Rot	TRANS LOC # MISSING	☐
426	23700	1696315.713	1147743.085	Shell Rot		☐
434	23658	1695931.444	1147089.555	Internal Decay		☐
443	0	1696676.769	1146842.554	Shell Rot		☐
464	857	1696583.779	1146295.059	Internal Decay	CWL & CENTURY LINK FIBER	☐
472	23630	1696589.836	1145525.78	Internal Decay	CWL & CENTURY LINK FIBER	☐
476	23608	1696616.418	1144935.501	Internal Decay	CWL & CENTURY LINK FIBER	☐
485	21782	1696455.219	1144079.057	Internal Decay		☐
489	21780	1696429.628	1143972.623	Internal Decay		☐
503	21777	1695914.663	1143716.422	Internal Decay		☐
513	21767	1695927.321	1144546.753	Shell Rot		☐
515	21768	1695925.868	1144693.865	Internal Decay		☐
525	21752	1695481.27	1144406.276	Internal Decay		☐
534	21756	1695480.436	1144987.294	Shell Rot		☐
545	21744	1695234.312	1144188.98	Internal Decay		☐
572	21723	1694659.157	1144333.129	Internal Decay		☐
574	21721	1694661.083	1144480.063	Internal Decay		☐
575	21720	1694678.508	1144602.631	Shell Rot		☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 1 of 3

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
576	21719	1694662.776	1144632.094	Shell Rot		☐
578	21728	1694678.046	1144828.7	Internal Decay		☐
581	3212	1694831.599	1144607	Shell Rot		☐
586	21739	1695061.255	1144596.702	Shell Rot		☐
588	3213	1695236.201	1144597.754	Heart Rot		☐
596	3208	1695409.269	1144842.333	Heart Rot	PRIORITY (CALLED IN)	☐
629	23547	1692367.085	1145776.908	Shell Rot		☐
646	21196	1693959.742	1144125.53	Shell Rot		☐
665	4079	1693671.865	1143616.057	Shell Rot		☐
666	21166	1693542.896	1143604.455	Internal Decay		☐
667	21165	1693540.698	1143517.674	Shell Rot		☐
668	21164	1693543.232	1143438.431	Internal Decay		☐
669	21163	1693542.793	1143358.585	Shell Rot		☐
711	3616	1692173.221	1143112.616	Internal Decay		☐
713	3618	1692189.358	1142922.648	Internal Decay	CWL & SHO-ME FIBER	☐
721	21626	1692294.992	1143054.855	Shell Rot		☐
728	21348	1692700.422	1142905.147	Heart Rot	PRIORITY (CALLED IN)	☐
730	21346	1692703.711	1143070.243	Internal Decay		☐
746	21366	1693079.242	1142677.259	Internal Decay		☐

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
753	21417	1693267.911	1142836.14	Internal Decay		☐
755	21415	1693266.71	1142682.868	Internal Decay		☐
759	21427	1693548.102	1142711.123	Internal Decay		☐
770	9533	1691574.265	1143831.726	Shell Rot		☐
809	21155	1695226.946	1143122.845	Shell Rot	CUSTOMER SAYS LIGHT NOT WORKING	☐
837	21056	1705933.556	1160721.926	Shell Rot		☐

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
883	18345	1705002.939	1156619.636	Heart Rot	CWL & SOCKET FIBER	☐
886	18342	1704847.248	1156291.397	Heart Rot	CWL & SOCKET FIBER	☐
902	2193	1704171.598	1155208.143	Shell Rot		☐
910	18335	1704097.985	1155168.554	Shell Rot		☐
924	18315	1704019.626	1154120.4	Heart Rot		☐
931	18308	1704323.503	1155179.357	Internal Decay	CWL & SOCKET FIBER	☐
960	21098	1706294.319	1161337.093	Internal Decay		☐
1023	0	1708296.037	1159590.797	Heart Rot	CWL & CENTURY LINK FIBER	☐
1034	18391	1708207.205	1157885.379	Woodpecker Damage		☐
1036	18389	1708197.82	1157531.99	Shell Rot		☐
1037	18388	1708185.648	1157363.003	Woodpecker Damage		☐
1038	18387	1708174.455	1157187.907	Internal Decay		☐
1041	18384	1707653.172	1157206.279	Internal Decay		☐
1050	18376	1706628.801	1157236.933	Heart Rot	CWL & CENTURY LINK FIBER	☐
1053	18355	1706145.899	1157228.929	Shell Rot	CWL & CENTURY LINK FIBER	☐
1081	21018	1710517.225	1158347.972	Internal Decay	CWL & CENTURY LINK FIBER	☐
1083	2326	1710734.438	1158226.792	Internal Decay		☐
1213	20509	1702680.357	1134751.811	Shell Rot	CWL & CENTURY LINK FIBER	☐
1229	20693	1703493.29	1137322.496	Top Rotten		☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 1 of 2

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
1237	20493	1701795.314	1134959.114	Shell Rot		☐

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
1271	20824	1705885.523	1138366.927	Internal Decay		☐
1302	1303	1704207.75	1139826.586	Shell Rot	CHARTER,MEDIA COM	☐
1360	18121	1705628.945	1141656.791	Internal Decay		☐
1361	18122	1705624.68	1141808.229	Shell Rot		☐
1372	20710	1701907.578	1138568.615	Shell Rot	CWL, SOCKET, CENTURY LINK FIBER	☐
1382	20704	1702619.608	1138592.325	Shell Rot	SOCKET, CENTURY LINK FIBER	☐
1395	20676	1701567.158	1138540.054	Heart Rot	CWL, SOCKET, CENTURY LINK FIBER	☐
1470	17908	1705483.979	1143751.42	Shell Rot		☐
1517	20591	1702034.403	1132259.01	Shell Rot		☐
1525	18074	1709945.855	1148390.286	Internal Decay		☐
1529	18071	1709652.071	1148723.07	Shell Rot		☐
1540	18049	1709656.313	1149145.078	Internal Decay		☐
1547	18054	1709004.177	1149542.448	Internal Decay		☐
1592	20472	1700516.065	1134436.17	Shell Rot		☐
1607	20623	1700211.334	1135241.323	Heart Rot		☐
1623	23063	1699808.811	1145321.208	Shell Rot	TRANS LOC # PRESENT BUT COULDN'T BE READ	☐
1628	23081	1699653.107	1145512.529	Internal Decay		☐
1630	23078	1699806.798	1145591.997	Shell Rot	TRANS LOC FADED	☐
1632	23077	1699897.586	1145413.224	Heart Rot		☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 1 of 2

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
1633	23075	1699982.764	1145559.168	Internal Decay		☐
1637	23067	1700282.66	1145666.587	Internal Decay		☐
1639	23071	1700336.429	1145721.393	Shell Rot		☐
1641	18065	1708022.231	1150199.31	Shell Rot		☐
1666	17951	1709870.477	1147770.639	Shell Rot		☐
1669	23033	1701181.305	1146434.493	Internal Decay		☐
1671	17948	1709425.556	1147783.501	Shell Rot		☐
1708	23055	1700495.226	1145148.665	Shell Rot	LIGHT IS FED FROM BOONE	☐
1712	21545	1702846.586	1154567.743	Shell Rot		☐
1728	21551	1701733.547	1154098.376	Shell Rot		☐

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
1769	3705	1691845.851	1139879.036	Shell Rot		☐
1770	3704	1691914.582	1139876.522	Heart Rot		☐
1772	3776	1691487.865	1139962.993	Shell Rot		☐
1775	608	1691412.344	1139883.101	Shell Rot		☐
1798	3711	1691030.274	1139888.489	Shell Rot		☐
1800	5015	1691024.961	1139806.11	Internal Decay		☐
1804	5090	1690840.555	1139781.577	Heart Rot		☐
1815	3771	1690886.333	1139971.068	Shell Rot	CENTURY LINK, CHARTER FIBER	☐
1846	590	1689707.189	1140003.037	Heart Rot		☐
1857	3721	1689896.846	1139916.478	Top Rotten		☐
1859	3722	1689776.029	1139914.293	Heart Rot		☐
1860	3723	1689659.359	1139916.146	Heart Rot		☐
1867	3759	1689586.637	1139986.504	Internal Decay	SOCKET, CHARTER FIBER	☐
1870	3758	1689378.284	1139989.123	Shell Rot	SOCKET, CHARTER FIBER	☐
1873	3757	1689193.853	1139992.207	Internal Decay	SOCKET, CHARTER FIBER	☐
1886	5843	1688944.777	1139878.16	Internal Decay	SOCKET, MEDIA COM, CHARTER, CENTURY LINK	☐
1888	3728	1689071.733	1139917.82	Shell Rot		☐
1894	7279	1688891.527	1139753.9	Shell Rot		☐
1896	5846	1688942.574	1139525.682	Internal Decay	CWL, CHARTER, MEDIA COM CENTURY LINK FIBER	☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 1 of 2

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
1910	21564	1700442.834	1151218.424	Shell Rot		☐
1912	5850	1688934.855	1139236.344	Heart Rot	SOCKET, CHARTER, MEDIA COM CENTURY LINK	☐
1953	21539	1701121.74	1153375.914	Internal Decay		☐
1977	5852	1688934.175	1138996.322	Internal Decay	SOCKET, CHARTER, MEDIA COM CENTURY LINK	☐
1979	5854	1688930.781	1138795.777	Shell Rot	SOCKET, CHARTER, MEDIA COM CENTURY LINK	☐
1994	5939	1689612.944	1138571.383	Shell Rot		☐
2004	5857	1688810.318	1138642.371	Internal Decay	SOCKET, CHARTER, MEDIACOM, & CENTURY LINK	☐
2033	20879	1708706.842	1142357.291	Woodpecker Damage		☐
2035	20880	1708908.265	1142356.455	Shell Rot		☐
2051	5863	1688293.37	1138552.39	Shell Rot	CENTURY LINK & MEDIACOM FIBER	☐
2069	18249	1704157.17	1139701.68	Heart Rot		☐
2084	18227	1704346.484	1139485.426	Internal Decay		☐
2089	18232	1704032.735	1139494.019	Shell Rot		☐
2135	18223	1704561.864	1139562.525	Internal Decay		☐
2152	5914	1688978.231	1137665.7	Heart Rot		☐
2167	18091	1707289.173	1149020.57	Shell Rot		☐
2190	18107	1703929.882	1149167.256	Woodpecker Damage		☐
2195	18103	1704832.621	1149000.287	Woodpecker Damage		☐
2199	6644	1688242.799	1137295.6	Heart Rot		☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 2 of 2

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
2229	5993	1689261.246	1137337.591	Heart Rot		☐
2237	7266	1689249.936	1137000.423	Heart Rot		☐
2248	6865	1689115.037	1136863.195	Internal Decay		☐
2249	6864	1689156.28	1136901.022	Internal Decay		☐
2260	6804	1688452.278	1136890.616	Shell Rot		☐
2263	6806	1688294.133	1136896.615	Shell Rot		☐
2273	6660	1689506.782	1137234.958	Shell Rot	CWL, CENTURY LINK FIBER	☐
2275	28036	1689464.474	1137284.499	Shell Rot		☐
2283	6845	1689454.65	1136640.423	Internal Decay		☐
2284	6846	1689480.735	1136628.689	Heart Rot		☐
2288	2360	1689697.331	1137210.973	Shell Rot	CWL, CENTURY LINK FIBER	☐
2290	23263	1689451.68	1136371.22	Internal Decay	CWL, CENTURY LINK FIBER	☐
2291	6842	1689497.13	1136440.374	Shell Rot	CWL, CENTURY LINK FIBER	☐
2317	6791	1687598.667	1137410.67	Internal Decay	CWL, SOCKET, CENTURY LINK FIBER	☐
2327	7574	1693328.383	1139492.206	Shell Rot		☐
2328	7573	1693374.619	1139512.441	Internal Decay		☐
2334	9230	1687733.297	1137288.521	Internal Decay		☐
2341	6678	1687818.286	1137360.639	Shell Rot		☐
2352	7747	1692637.487	1138902.691	Heart Rot		☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 1 of 5

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
2359	2344	1688352.436	1137181.869	Shell Rot		☐
2363	7271	1688558.079	1137122.598	Shell Rot		☐
2364	6643	1688277.07	1137099.185	Internal Decay		☐
2367	6645	1688276.872	1137017.894	Internal Decay		☐
2371	28004	1692425.412	1138632.745	Internal Decay		☐
2402	6241	1691809.782	1138485.204	Shell Rot		☐
2406	6901	1688910.111	1136631.108	Heart Rot		☐
2407	8918	1691858.742	1139148.689	See Remarks	PRIORITY-POLE ROTTED OFF BELOW GROUND	☐
2413	609	1691943.907	1139262.482	Shell Rot		☐
2415	6239	1691843.476	1138330.022	Internal Decay		☐
2423	3518	1691340.536	1138038.466	Shell Rot		☐
2431	894	1688221.518	1136359.43	Internal Decay	CWL, CENTURY LINK FIBER	☐
2450	5585	1691532.119	1137541.126	Heart Rot		☐
2463	6880	1689817.223	1136828.18	Shell Rot	CHARTER, CENTURY LINK FIBER	☐
2468	6263	1691222.473	1137782.515	Shell Rot		☐
2473	6260	1691246.97	1138036.137	Internal Decay		☐
2477	6259	1691331.589	1138462.836	Shell Rot		☐
2479	6271	1691262.845	1138338.592	Internal Decay		☐
2480	6270	1691260.065	1138273.874	Shell Rot		☐

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
2507	6654	1690080.552	1137161.945	Internal Decay	WL, MEDIA COM, CENTURY LINK, UNKNOWN FIBE	☐
2525	6648	1690478.258	1137113.986	Shell Rot	MEDIA COM, CENTURY LINK FIBER	☐
2526	6211	1692866.509	1137862.32	Internal Decay		☐
2529	6825	1690540.479	1136965.694	Shell Rot	MEDIA COM, CENTURY LINK FIBER	☐
2533	6208	1693157.118	1137866.562	Internal Decay		☐
2540	28044	1690586.021	1137220.319	Shell Rot	MEDIA COM, CENTURY LINK FIBER	☐
2579	9264	1690829.38	1137740.929	Shell Rot	#6 TRIPLEX, SHO-ME, SOCKET, CENTURY LINK FI	☐
2608	4535	1692323.533	1137769.287	Heart Rot		☐
2610	4536	1692310.89	1137863.444	Heart Rot		☐
2625	5531	1692692.085	1138397.082	Internal Decay		☐
2649	5514	1693187.846	1138275.227	Shell Rot	CABLE POWER SUPPLY	☐
2651	324	1693043.201	1138188.284	Shell Rot		☐
2669	6202	1693522.281	1137855.806	Internal Decay		☐
2702	10737	1693894.19	1138554.729	Shell Rot		☐
2709	10736	1693942.854	1138741.535	Shell Rot		☐
2749	6186	1685626.192	1139589.921	Heart Rot	SOCKET, CENTURY LINK FIBER	☐
2765	6171	1685617.823	1139168.344	Heart Rot		☐
2782	5456	1694404.992	1139263.701	Heart Rot		☐
2791	5483	1693896.538	1139266.939	Shell Rot		☐

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
2795	4629	1685237.637	1139546.93	Shell Rot		☐
2801	5714	1686150.258	1139842.119	Internal Decay		☐
2808	1787	1693958.497	1138658.125	Shell Rot	PRIORITY REJECT	☐
2810	1786	1693956.801	1138614.573	Shell Rot	PRIORITY REJECT	☐
2816	5457	1694109.91	1138658.504	Internal Decay		☐
2818	5530	1693910.305	1138076.703	Shell Rot		☐
2824	5534	1693859.027	1137826.073	Shell Rot		☐
2826	5771	1686546.301	1140199.313	Shell Rot		☐
2836	5541	1693840.328	1137343.099	Internal Decay		☐
2846	5614	1686288.431	1138468.046	Internal Decay		☐
2856	5547	1693458.286	1137450.935	Internal Decay		☐
2872	5723	1686243.736	1138037.405	Heart Rot		☐
2876	2762	1694381.712	1139791.145	Shell Rot		☐
2879	1793	1694311.896	1139554.875	Shell Rot		☐
2930	6929	1686225.206	1137307.41	Internal Decay		☐
2931	3038	1686256.495	1137242.085	Internal Decay	CWL, MEDIA COM, CENTURY LINK FIBER	☐
2938	3880	1686835.583	1137178.452	Heart Rot	MEDIA COM, CENTURY LINK FIBER	☐
2954	3866	1687173.188	1137130.295	Heart Rot		☐
2955	3847	1686941.004	1136769.878	Internal Decay		☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 4 of 5

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
2961	3033	1686244.783	1136753.424	Heart Rot	CWL, MEDIA COM FIBER	☐
2989	5357	1694896.302	1138319.636	Internal Decay		☐
2990	5361	1694919.75	1138254.753	Pole broken at groun	PRIORITY REJECT	☐
2995	7135	1685787.057	1136930.38	Internal Decay		☐
3003	6359	1695077.278	1138168.836	Internal Decay		☐
3037	28049	1686204.87	1136236.653	Internal Decay		☐
3047	7558	1695353.024	1138762.284	Heart Rot		☐
3054	5364	1695516.947	1138211.829	Shell Rot		☐
3062	5332	1695437.058	1138731.064	Heart Rot		☐
3070	4436	1688960.109	1140043.405	Internal Decay	CWL, SOCKET, CHARTER FIBER	☐
3082	752	1688693.151	1140039.538	Shell Rot	SOCKET, CHARTER, CENTURY LINK FIBER	☐
3084	3751	1688589.844	1140054.912	Internal Decay	SOCKET, CHARTER, CENTURY LINK FIBER	☐
3086	564	1688512.497	1140082.551	Internal Decay	CENTURY LINK & MEDIACOM FIBER	☐

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
3146	11107	1674190.528	1142229.492	Internal Decay	CENTURY LINK & MEDIACOM FIBER	☐
3153	5322	1694719.662	1138927.975	Heart Rot		☐
3159	5317	1694550.238	1138932.15	Heart Rot		☐
3161	5309	1694426.397	1138929.117	Heart Rot		☐
3167	3542	1694759.588	1139114.991	Shell Rot		☐
3175	11678	1673463.433	1141820.22	Shell Rot		☐
3180	11677	1673451.596	1141596.598	Internal Decay		☐
3201	3544	1694761.524	1139406.889	Shell Rot		☐
3293	6296	1693931.223	1136572.263	Shell Rot		☐
3297	6297	1694354.028	1136573.974	Shell Rot		☐
3302	6302	1694757.251	1136269.636	Shell Rot		☐
3305	27747	1694634.828	1136156.444	Shell Rot		☐
3315	6300	1694490.169	1136234.281	Shell Rot		☐
3320	6352	1695337.302	1136243.119	Internal Decay		☐
3322	6353	1695335.363	1136388.359	Shell Rot		☐
3323	6354	1695338.245	1136460.427	Internal Decay		☐
3331	10367	1675447.988	1142416.215	Shell Rot		☐
3389	12276	1676585.047	1144152.089	Shell Rot		☐
3391	12278	1676335.855	1144182.84	Internal Decay		☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 1 of 3

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
3421	11621	1677810.47	1144155.393	Shell Rot		☐
3451	7755	1691027.487	1140797.973	Internal Decay		☐
3454	4298	1691477.722	1140789.314	Internal Decay		☐
3470	12282	1676016.84	1145202.471	Heart Rot		☐
3471	12283	1676014.748	1145176.16	Shell Rot		☐
3477	12285	1675864.065	1145002.485	Internal Decay		☐
3495	11206	1675385.165	1144846.103	Heart Rot		☐
3501	11138	1675541.994	1144696.908	Heart Rot		☐
3503	11139	1675543.818	1144743.994	Heart Rot		☐
3509	11133	1675692.061	1144541.754	Heart Rot		☐
3526	6323	1696922.665	1136094.36	Shell Rot		☐
3527	6333	1697050.494	1136031.5	Shell Rot		☐
3541	11121	1675625.076	1143393.623	Heart Rot		☐
3542	11120	1675608.508	1143203.858	Heart Rot		☐
3554	12300	1675232.16	1144869.053	Internal Decay		☐
3559	11202	1675119	1144911.887	Top Rotten		☐
3576	11634	1676615.124	1144922.729	Internal Decay		☐
3587	11235	1674943.238	1144987.093	Top Rotten		☐
3616	12297	1675458.029	1145879.397	Heart Rot		☐

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
3623	11215	1675185.026	1145872.328	Heart Rot		☐
3630	6401	1692732.543	1136334.788	Shell Rot		☐
3644	11212	1675053.711	1145532.898	Internal Decay		☐
3646	11224	1674957.055	1145536.923	Internal Decay		☐
3648	4598	1674950.6	1145381.288	Heart Rot		☐
3674	11220	1674691.84	1145856.528	Internal Decay		☐
3682	5564	1692572.924	1137223.426	Internal Decay		☐
3684	5553	1693027.761	1137237.888	Internal Decay		☐

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
3689	6381	1693530.719	1136634.667	Shell Rot	1904 TAG ALSO	☐
3690	6387	1693082.084	1136877.197	Shell Rot		☐
3693	4313	1691647.901	1140318.372	Shell Rot		☐
3696	4316	1691842.194	1140270.027	Internal Decay		☐
3698	4352	1691936.762	1140307.509	Shell Rot		☐
3707	6613	1692472.266	1136463.685	Heart Rot	PRIORITY 207 WILLIAM ST	☐
3721	6473	1692173.589	1136272.148	Internal Decay		☐
3727	6479	1692061.211	1136841.676	Heart Rot		☐
3733	6632	1692052.324	1136751.742	Internal Decay		☐
3774	6438	1691606.215	1136450.55	Top Rotten		☐
3793	6429	1691579.816	1137136.241	Shell Rot		☐
3801	7729	1691274.847	1137205.519	Internal Decay		☐
3822	4291	1692422.435	1141151.142	Internal Decay		☐
3834	4296	1691880.646	1141159.057	Shell Rot		☐
3846	6475	1692338.913	1136245.661	Heart Rot		☐
3848	6454	1691430.643	1136216.186	Internal Decay		☐
3852	6406	1692508.861	1135924.196	Internal Decay		☐
3856	7503	1691577.383	1136149.985	Heart Rot		☐
3866	6413	1692123.247	1135717.645	Splits and Checks		☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 1 of 5

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
3879	6416	1691833.223	1135717.767	Shell Rot		☐
3900	6448	1691759.829	1136234.131	Internal Decay		☐
3918	535	1692410.703	1135573.902	Heart Rot		☐
3923	6372	1693543.675	1135672.028	Shell Rot	CENTURY LINK/CWL FIBER	☐
3939	2206	1695182.452	1141749.941	Shell Rot		☐
3954	2032	1691551.816	1140735.968	Top Rotten		☐
3956	7763	1691525.379	1140788.401	Shell Rot		☐
3959	7766	1692281.077	1140241.948	Shell Rot		☐
3960	7767	1692339.437	1140187.733	Internal Decay		☐
3961	28083	1692322.194	1140293.871	Internal Decay		☐
3987	7780	1692755.039	1140453.863	Top Rotten		☐
3988	6706	1691116.764	1136650.864	Internal Decay	SHO-ME/CHARTER/SOCKET FIBER	☐
3989	7779	1692740.704	1140522.96	Shell Rot		☐
3993	7777	1692744.232	1140778.284	Shell Rot		☐
3997	7782	1692622.918	1140457.893	Internal Decay		☐
3998	6754	1690707.313	1136179.885	Internal Decay	WL, CHARTER, CENTURY LINK FIBER	☐
4009	6746	1690590.185	1136016.393	Heart Rot		☐
4017	6777	1690791.223	1136273.868	Internal Decay		☐
4021	6775	1690789.815	1136377.733	Heart Rot		☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 2 of 5

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
4033	7527	1690794.265	1136579.521	Pole broken at groun	PRIORITY 305 N SAINT JOSEPH ST	☐
4039	6769	1690795.498	1136669.666	Pole broken at groun	PRIORITY 307 N SAINT JOSEPH	☐
4049	21381	1694097.102	1141658.314	Shell Rot		☐
4066	6696	1690883.08	1136997.021	Shell Rot		☐
4069	2354	1690796.874	1136938.094	Shell Rot	SOCKET, CENTURY LINK FIBER	☐
4072	5994	1691130.279	1137156.313	Shell Rot	SHO-ME/SOCKET FIBER	☐
4077	5995	1691132.15	1137240.454	Shell Rot	SOCKET/SHO-ME/CHARTER FIBER	☐
4089	1751	1698350.898	1143773.298	Internal Decay		☐
4123	21302	1698122.519	1143519.54	Shell Rot		☐
4137	1083	1690768.352	1138340.02	Internal Decay		☐
4138	5005	1691214.675	1138609.502	Heart Rot		☐
4152	21123	1697872.588	1143483.532	Shell Rot		☐
4153	27212	1697738.294	1143540.612	Shell Rot		☐
4191	2303	1690498.907	1138240.089	Shell Rot		☐
4210	2380	1690444.3	1137892.834	Shell Rot		☐
4213	2381	1690580.183	1137892.353	Shell Rot		☐
4267	5120	1690214.422	1138642.179	Shell Rot		☐
4272	28075	1690217.817	1138812.071	Shell Rot		☐
4274	2197	1697382.789	1144541.361	Internal Decay		☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 3 of 5

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
4275	23146	1697452.722	1144559.506	Shell Rot	UNDERBUILD	☐
4283	23145	1697230.989	1144516.045	Internal Decay		☐
4295	5114	1690225.195	1139207.53	Shell Rot		☐
4299	5101	1690375.735	1139277.249	Shell Rot	CWL, SOCKET, SHO-ME, CENTURY LINK FIBER	☐
4305	5112	1690232.441	1139385.706	Heart Rot	CWL, SOCKET, SHO-ME FIBER	☐
4326	5109	1690235.262	1139699.11	Shell Rot		☐
4333	5103	1690259.61	1139417.315	Internal Decay		☐
4341	5105	1690263.293	1139543.593	Internal Decay		☐
4345	5032	1689748.377	1138662.935	Heart Rot		☐
4351	5031	1689772.477	1138759.968	Heart Rot		☐
4356	5030	1689798.703	1138871.318	Shell Rot		☐
4362	5028	1689821.743	1138971.972	Shell Rot		☐
4366	5832	1689806.01	1139011.406	Shell Rot		☐
4368	5027	1689850.106	1139079.155	Heart Rot	PRIORITY 1000 B EIGHTH ST	☐
4372	5833	1689828.949	1139119.075	Shell Rot		☐
4376	7744	1690072.446	1139722.808	Shell Rot		☐
4380	5025	1689894.889	1139274.964	Shell Rot		☐
4435	5891	1687914.757	1138095.726	Shell Rot		☐
4441	27573	1698710.393	1143987.373	Shell Rot		☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 4 of 5

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
4442	23127	1698551.088	1143981.271	Shell Rot		☐
4448	5812	1687612.337	1138454.132	Shell Rot	CWL, SOCKET, CENTURY LINK FIBER	☐
4452	28061	1688179.27	1137775.885	Shell Rot	PRIORITY 407 HICKMAN AVE	☐
4454	2789	1698394.527	1143979.426	Shell Rot		☐
4458	23187	1698680.005	1144147.419	Heart Rot		☐
4461	5814	1687607.638	1138251.573	Heart Rot	CWL, SOCKET, CENTURY LINK FIBER	☐
4463	7280	1687676.25	1138202.377	Shell Rot		☐
4468	5820	1687598.478	1137548.577	Heart Rot	CWL/CENTURY LINK/CHARTER FIBER	☐
4475	9229	1687849.27	1137626.517	Heart Rot		☐
4477	5818	1687601.234	1137740.45	Internal Decay	CWL, SOCKET, CENTURY LINK FIBER	☐
4564	7914	1696107.508	1141884.231	Shell Rot		☐
4575	5763	1686888.723	1139560.545	Shell Rot		☐
4619	21984	1697991.962	1142017.878	Heart Rot		☐
4643	6145	1685204.62	1138906.459	Heart Rot		☐
4647	7157	1685123.161	1140106.843	Internal Decay		☐
4649	1527	1685329.06	1140195.567	Shell Rot		☐
4652	6158	1685010.055	1140008.817	Shell Rot		☐
4656	4627	1684918.343	1139701.595	Top Rotten		☐
4663	6149	1684895.918	1139119.67	Top Rotten		☐

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
4655	21384	1694452.355	1141639.703	Heart Rot		☐
4707	6132	1685526.396	1138800.622	Shell Rot		☐
4709	6134	1685733.189	1138752.442	Shell Rot		☐
4728	2131	1687447.979	1138346.302	Shell Rot		☐
4730	5633	1687552.824	1138275.794	Shell Rot		☐
4738	5650	1686793.156	1138427.021	Internal Decay		☐
4742	1548	1686589.239	1138264.411	Shell Rot		☐
4743	1547	1686591.108	1138366.834	Internal Decay	CCTV RISER	☐
4766	5685	1687070.958	1138164.771	Shell Rot		☐
4768	5683	1687065.21	1137999.98	Shell Rot		☐
4788	6938	1685518.114	1137828.343	Shell Rot		☐
4798	634	1685658.902	1141464.96	Shell Rot		☐
4807	7170	1686231.88	1141698.825	Heart Rot		☐
4817	4922	1686721.963	1141278.024	Shell Rot		☐
4836	9276	1687019.329	1140853.713	Shell Rot		☐
4841	4904	1686989.776	1140568.446	Internal Decay		☐
4851	4477	1687343.997	1140976.437	Shell Rot	CENTURY LINK/SOCKET FIBER	☐
4853	4486	1687298.86	1140907.125	Shell Rot		☐
4865	4474	1687371.091	1140862.811	Internal Decay		☐

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
4892	4409	1690216.591	1140358.053	Internal Decay	CWL/SHO ME FIBER	☐
4896	4398	1690213.921	1140237.303	Shell Rot	CWL/SHO ME FIBER	☐
4900	3765	1690201.515	1139978.267	Shell Rot		☐
4924	4449	1688713.497	1141104.118	Shell Rot		☐
4926	2047	1688703.462	1140878.255	Shell Rot		☐
4932	4456	1688453.328	1140709.109	Shell Rot	CENTURY LINK/SOCKET FIBER	☐
4953	9272	1687967.466	1140440.906	Shell Rot		☐

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
4977	7164	1684794.007	1141669.112	Shell Rot	PRIORITY NE PARKADE SIGN	☐
5048	6062	1684523.759	1140220.553	Internal Decay		☐
5050	6026	1683808.215	1139945.102	Internal Decay		☐
5051	7149	1683799.318	1140109.058	Internal Decay		☐
5063	6006	1683407.585	1140253.043	Shell Rot		☐
5072	6017	1683842.335	1139844.843	Shell Rot		☐
5099	1632	1683121.856	1140374.089	Internal Decay		☐
5122	5230	1682335.209	1139580.798	Heart Rot		☐
5269	5261	1682325.075	1138875.36	Shell Rot		☐
5276	5267	1682336.091	1139500.358	Shell Rot	SOCKET/CWL FIBER	☐
5284	6998	1685230.709	1136799.478	Heart Rot		☐
5286	6501	1685231.509	1136505.491	Internal Decay		☐
5289	6953	1684865.865	1136801.477	Shell Rot		☐
5296	6946	1684857.38	1137534.665	Shell Rot		☐
5303	6566	1684382.462	1137972.605	Heart Rot		☐
5307	6572	1684476.801	1137754.867	Internal Decay		☐
5308	6573	1684477.448	1137653.864	Heart Rot		☐
5311	6575	1684478.403	1137446.727	Heart Rot		☐
5313	6578	1684506.723	1137257.725	Heart Rot	PRIORITY 312 SANFORD AVE	☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 1 of 2

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
5314	6577	1684478.115	1137242.698	Top Rotten		☐
5337	7029	1683791.148	1136830.811	Shell Rot		☐
5340	7031	1683792.744	1137057.008	Shell Rot		☐
5341	7032	1683795.063	1137157.845	Shell Rot		☐
5344	7036	1683802.083	1137485.854	Shell Rot		☐
5346	7038	1683806.911	1137678.365	Shell Rot		☐
5351	7043	1684027.946	1138023.107	Heart Rot		☐
5355	4656	1682802.152	1137069.511	Shell Rot		☐
5363	7085	1683328.378	1137151.368	Heart Rot		☐
5370	4696	1683447.28	1137402.932	Shell Rot		☐
5380	4636	1683409.856	1138100.222	Heart Rot	PRIORITY 714 WEST WORLEY	☐
5385	7130	1682923.944	1138157.171	Internal Decay		☐
5400	4689	1682499.341	1137875.994	Internal Decay		☐

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
5462	7109	1682267.946	1135632.221	Internal Decay		☐
5472	4645	1682920.487	1135944.531	Shell Rot		☐
5481	422	1683196.016	1135721.875	Shell Rot		☐
5491	28302	1683312.319	1136115.185	Heart Rot		☐
5505	7069	1683586.062	1136673.149	Heart Rot		☐
5517	7026	1683858.029	1136626.947	Shell Rot		☐
5529	7012	1683854.043	1135576.452	Shell Rot		☐
5537	7007	1684456.702	1135480.994	Shell Rot		☐
5546	7002	1684817.041	1135880.674	Shell Rot		☐
5560	6589	1684353.866	1136543.388	Internal Decay		☐
5566	6957	1684869.269	1136354.21	Internal Decay		☐
5570	6961	1684870.455	1135859.85	Internal Decay		☐
5578	6966	1685005.699	1135317.484	Shell Rot		☐
5584	6506	1685240.33	1135908.286	Heart Rot		☐
5593	6530	1685355.116	1136383.319	Internal Decay		☐
5595	317	1685643.563	1136337.841	Shell Rot		☐
5612	6535	1686048.538	1136269.931	Shell Rot		☐
5620	3252	1685825.908	1136087.378	Internal Decay		☐
5623	6544	1686061.368	1135519.525	Shell Rot		☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 1 of 2

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
5624	6543	1686068.747	1135659.845	Shell Rot		☐
5632	6546	1685472.149	1135454.556	Shell Rot		☐
5638	3253	1685586.825	1135867.06	Shell Rot		☐
5643	6548	1685617.324	1136114.694	Shell Rot		☐
5647	3255	1685570.958	1135677.361	See Remarks	SPLITS/EXCESSIVE SWEEP	☐
5648	4641	1685373.655	1135957.606	Shell Rot		☐
5650	350	1685609.271	1136584.606	Shell Rot		☐
5671	6982	1685301.491	1137546.695	Internal Decay		☐
5674	2076	1685495.547	1137520.526	Shell Rot		☐
5687	3820	1686565.167	1136457.173	Heart Rot		☐
5698	27760	1686806.52	1136882.819	Shell Rot		☐
5699	3833	1687139.747	1136678.672	Top Split Out		☐
5722	3884	1687260.147	1136272.775	Heart Rot		☐
5733	3852	1687409.329	1136748.185	Shell Rot		☐
5745	3389	1687316.405	1136144.818	Shell Rot		☐
5773	3393	1687553.684	1135992.974	Shell Rot		☐

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
5809	6823	1688840.894	1136237.552	Internal Decay		☐
5836	1640	1680538.601	1139887.446	Heart Rot		☐
5882	11264	1675110.711	1144619.687	Shell Rot		☐
5895	11268	1675018.087	1144508.402	Shell Rot		☐
5896	11267	1674959.755	1144669.193	Top Rotten		☐
5925	11250	1674815.155	1143546.815	Shell Rot		☐
5934	11256	1675181.778	1143544.897	Shell Rot		☐
5967	14184	1681919.778	1139273.357	Internal Decay		☐
5968	11284	1674779.949	1143028.276	Internal Decay		☐
5980	14153	1681024.739	1139041.497	Heart Rot		☐
6005	9516	1676936.965	1145847.323	Shell Rot		☐
6006	11650	1676838.128	1145691.343	Shell Rot		☐
6007	11651	1676839.686	1145687.201	Shell Rot		☐
6011	11653	1676815.189	1145653.948	Shell Rot		☐
6015	14152	1680731.97	1138886.212	Top Rotten		☐
6019	11657	1676713.823	1145562.908	Shell Rot	PRIORITY REJECT CALLED IN	☐
6049	14129	1680041.814	1139649.632	Shell Rot		☐
6054	928	1674337.56	1144208.341	Heart Rot		☐
6068	11242	1674557.172	1144231.582	Top Rotten		☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 1 of 3

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
6097	14099	1679612.17	1139578.811	Heart Rot		☐
6158	11508	1679004.257	1139205.269	Shell Rot		☐
6161	1328	1678981.694	1139087.042	Shell Rot		☐
6165	2311	1677890.128	1145095.033	Top Rotten		☐
6167	2312	1677803.971	1145049.399	Shell Rot		☐
6168	2313	1677831.385	1144951.651	Internal Decay		☐
6182	11510	1678994.299	1138869.389	Shell Rot		☐
6198	12512	1677344.781	1147233.407	Shell Rot	CWL, CENTURY LINK, CHARTER & UNKNOWN FIBE	☐
6206	12516	1677326.36	1147479.311	Internal Decay	CWL, CENTURY LINK, CHARTER & UNKNOWN FIBE	☐
6226	12390	1677194.324	1140626.783	Heart Rot		☐
6237	12198	1677382.608	1146480.361	Internal Decay		☐
6268	14495	1680161.388	1144823.126	Shell Rot	NO TRANS LOC #	☐
6269	2964	1677630.734	1138137.282	Internal Decay	SOCKET/CENTURY LINK/CWL FIBER	☐
6273	2963	1677627.78	1137881.225	Internal Decay		☐
6301	2962	1677625.382	1137657.404	Heart Rot		☐
6311	12397	1678654.146	1139979.784	Shell Rot		☐
6317	12400	1679018.48	1139948.491	Shell Rot		☐
6347	14475	1681234.093	1143159.274	Heart Rot		☐
6348	14477	1681219.598	1142994.299	Heart Rot		☐

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
6361	14462	1681944.375	1142944.555	Shell Rot		☐

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
6381	7230	1682263.711	1141972.236	Shell Rot	TRANS LOC # MISSING	☐
6385	7224	1682338.67	1142012.702	Shell Rot		☐
6386	11586	1678618.041	1138666.131	Shell Rot		☐
6417	1017	1679552.476	1137947.986	Shell Rot		☐
6451	14360	1682409.75	1142233.928	Internal Decay	DM & CHARTER CABLE, CENTURY LINK & MEDIAC	☐
6486	14350	1682962.92	1142184.94	Internal Decay		☐
6503	14405	1682846.416	1142576.373	Top Rotten		☐
6504	14059	1679805.518	1138526.241	Internal Decay		☐
6539	9943	1680785.644	1137526.517	Shell Rot		☐
6555	9905	1680794.798	1137104.071	Shell Rot		☐
6556	9902	1680716.533	1137113.387	Shell Rot		☐
6563	7239	1683505.212	1141956.482	Top Rotten	TRANS LOC # MISSING	☐
6566	8690	1679999.695	1137330.885	Internal Decay		☐
6596	9935	1680908.249	1136740.029	Internal Decay		☐
6609	14398	1683081.363	1142553.145	Lightning Strike		☐
6618	14331	1683363.453	1142568.842	Top Rotten		☐
6660	14342	1683916.743	1142369.312	Heart Rot	TRANS LOC # MISSING	☐
6670	14043	1681677.828	1138307.488	Heart Rot		☐
6679	14038	1682108.042	1138264.534	Shell Rot		☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 1 of 3

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
6682	7249	1683773.425	1141878.837	Internal Decay		☐
6720	14325	1683289.6	1143113.266	Internal Decay		☐
6740	9954	1681060.03	1137348.028	Heart Rot		☐
6743	9955	1681055.406	1137250.966	Heart Rot		☐
6759	14376	1682562.641	1142968.42	Shell Rot		☐
6766	14378	1682452.192	1143164.476	Internal Decay	OM & CHARTER CABLE, MEDIACOM & CENTURY LI	☐
6788	453	1678820.988	1136412.92	Shell Rot	CWL/SOCKET FIBER	☐
6792	456	1678912.121	1136563.796	Shell Rot		☐
6847	7253	1683259.711	1141482.432	Shell Rot		☐
6871	14513	1682705.5	1143411.911	Internal Decay		☐
6879	374	1677255.955	1136949.106	Shell Rot		☐
6893	3068	1684574.494	1142607.764	Heart Rot		☐
6894	14223	1684586.409	1142697.828	Heart Rot		☐
6912	13184	1681918.538	1136432.612	Heart Rot		☐
6919	13186	1681921.277	1136261.394	Internal Decay		☐
6938	14274	1684699.74	1143598.766	Heart Rot		☐
6974	10679	1681309.682	1136835.288	Shell Rot		☐
6983	1843	1686185.752	1141977.773	Shell Rot		☐
7019	836	1677963.49	1141399.194	Heart Rot	CHARTER/SOCKET FIBER	☐

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
7034	11548	1678277.505	1141036.527	Shell Rot		☐
7057	4236	1678891.254	1141271.755	Heart Rot	CHARTER/SOCKET FIBER	☐
7060	4233	1679167.383	1141235.96	Internal Decay	CHARTER/SOCKET FIBER	☐
7075	11559	1679188.452	1140619.434	Heart Rot	PRIORITY CALLED IN	☐
7077	11560	1679020.902	1140696.4	Internal Decay		☐
7078	11561	1678864.982	1140771.471	Shell Rot		☐
7081	1340	1679341.068	1141058.213	Shell Rot		☐
7101	4264	1679672.698	1140776.261	Heart Rot		☐
7103	1337	1679886.872	1140737.191	Shell Rot		☐
7111	14267	1685577.629	1143602.901	Shell Rot		☐
7115	10550	1685793.891	1143602.459	Internal Decay		☐
7116	4219	1679895.375	1141135.853	Heart Rot		☐
7153	288	1680295.986	1141091.225	Shell Rot		☐
7187	4199	1681698.678	1140908.271	Shell Rot	CWL/SOCKET FIBER	☐

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
7195	481	1675715	1136869.235	Shell Rot		☐
7201	477	1675729.869	1137353.156	Shell Rot		☐
7208	473	1676026.175	1137204.066	Shell Rot	SECURITY LIGHT OUT	☐
7240	12545	1676239.135	1137388.979	Internal Decay		☐
7242	12535	1676300.431	1137380.427	Shell Rot		☐
7244	12536	1676313.99	1137307.691	Shell Rot		☐
7270	10580	1686693.346	1144655.463	Shell Rot		☐
7275	12591	1676698.557	1136961.736	Shell Rot		☐
7277	12589	1676565.913	1136980.709	Shell Rot		☐
7284	12582	1676320.081	1136763.38	Shell Rot		☐
7286	2581	1676320.342	1136522.022	Shell Rot	CENTURY LINK/SOCKET FIBER	☐
7297	12576	1676274.256	1136604.414	Shell Rot		☐
7301	12584	1676310.28	1137052.42	Internal Decay		☐
7302	12588	1676429.99	1136999.206	Heart Rot		☐
7305	12565	1676101.033	1136901.261	Shell Rot		☐
7306	12564	1676130.508	1136889.2	Shell Rot		☐
7307	12566	1676102.913	1137102.017	Shell Rot		☐
7308	470	1676108.424	1137304.081	Internal Decay		☐
7309	7498	1686425.38	1144955.737	Shell Rot		☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 1 of 3

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
7350	10501	1686883.609	1143201.876	Shell Rot		☐
7414	12557	1674953.639	1137655.678	Shell Rot	CWL/SOCKET/CHARTER FIBER	☐
7419	12560	1674424.866	1137710.267	Shell Rot	CWL/SOCKET/CHARTER FIBER	☐
7448	11605	1675868.186	1138521.097	Shell Rot	CWL/SOCKET/CHARTER FIBER	☐
7460	1901	1687264.035	1143335.166	Internal Decay	TRANS LOC # MISSING	☐
7467	2125	1687646.293	1142695.614	Heart Rot	CWL & SOCKET FIBER	☐
7490	10400	1676597.961	1139147.133	Heart Rot		☐
7491	11600	1676591.904	1139149.967	Heart Rot		☐
7496	4709	1675732.167	1139022.753	Shell Rot		☐
7510	9627	1686322.085	1142145.287	Heart Rot		☐
7515	10384	1675529.336	1140687.62	Shell Rot	CENTURY LINK/SOCKET/CHARTER FIBER	☐
7516	10383	1675723.465	1140664.122	Shell Rot	CENTURY LINK/SOCKET/CHARTER FIBER	☐
7522	26993	1687752.614	1142126.284	Heart Rot		☐
7526	1720	1676616.388	1140560.208	Internal Decay	SOCKET/CHARTER FIBER	☐
7535	10378	1676952.081	1140631.579	Internal Decay		☐
7539	9684	1686623.272	1142372.164	Internal Decay		☐
7636	8318	1681613.303	1146182.613	Internal Decay		☐
7667	10707	1688380.39	1142183.03	Shell Rot	PRIORITY REJECT CALLED IN	☐
7668	10708	1688380.322	1142013.883	Shell Rot		☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 2 of 3

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
7700	10442	1689196.155	1142792.647	Shell Rot		☐
7703	10440	1689197.236	1142995.224	Shell Rot		☐
7724	10455	1689579.262	1142561.015	Shell Rot	CWL, SHO ME & CENTURY LINK FIBER	☐
7732	12763	1664836.496	1135023.258	Top Rotten	8A CWC	☐

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
7896	12757	1666408.158	1134677.659	Heart Rot	8A CWC	☐
7950	10488	1689430.362	1143859.105	Heart Rot		☐
7951	10489	1689354.696	1143816.384	Shell Rot		☐
7974	9884	1690592.556	1143787.046	Heart Rot		☐
7977	156	1690314.675	1143805.231	Heart Rot		☐
7994	10493	1689295.478	1144445.035	Shell Rot		☐
7997	7522	1671356.477	1135485.982	Shell Rot		☐
8005	11495	1671579.543	1135425.749	Heart Rot	PRIORITY CALLED IN 312 STALCUP ST	☐
8008	11494	1671577.095	1135139.406	Shell Rot		☐
8011	11496	1671572.333	1134867.449	Shell Rot		☐
8013	11498	1671566.799	1134360.924	Shell Rot		☐
8025	9874	1690904.839	1143955.089	Woodpecker Damage		☐
8032	9899	1691127.017	1144049.502	Top Rotten		☐
8036	12733	1671044.686	1134518.847	Shell Rot		☐
8038	12734	1670902.49	1134741.051	Shell Rot		☐
8039	12735	1671053.461	1134735.522	Shell Rot		☐
8042	12717	1670757.862	1134958.198	Top Rotten		☐
8053	12701	1670258.389	1134598.137	Heart Rot		☐
8060	12719	1670478.584	1135135.571	Shell Rot		☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 1 of 2

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
8092	17723	1690228.434	1144884.222	Shell Rot		☐
8098	11431	1671022.376	1135640.269	Shell Rot		☐
8102	17722	1690032.481	1144891.127	Heart Rot	TRANS LOC MISSING	☐
8116	7646	1690530.052	1145442.692	Heart Rot		☐
8128	11425	1670829.885	1136053.853	Shell Rot		☐
8152	17727	1688925.364	1144712.728	Internal Decay		☐
8190	17715	1690035.003	1145083.526	Internal Decay		☐
8192	500	1670292.918	1136529.083	Shell Rot		☐
8216	11479	1669916.838	1135981.752	Shell Rot		☐
8241	11492	1669578.499	1136156.205	Heart Rot		☐
8255	11481	1669809.946	1136017.586	Shell Rot		☐
8293	21669	1697538.092	1140143.724	Heart Rot		☐
8313	21677	1697231.131	1140374.87	Heart Rot		☐
8318	21685	1697114.17	1140579.132	Top Rotten		☐
8319	21681	1697014.936	1140530.229	Heart Rot		☐
8327	21978	1697325.675	1142041.85	Shell Rot		☐
8328	21979	1697378.037	1141957.418	Top Rotten	TRANS LOC # MISSING	☐
8342	21690	1697489.113	1141020.218	Internal Decay		☐
8348	21968	1697367.875	1141511.421	Heart Rot	MER WANTS TO BE CONTACTED BEFORE REPLAC	☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 2 of 2

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
8367	12422	1673442.867	1133766.167	Heart Rot		☐
8370	12777	1672999.7	1133829.586	Shell Rot		☐
8380	12788	1673123.994	1132641.175	Top Rotten		☐
8383	24240	1673172.601	1133420.314	Heart Rot		☐
8384	12407	1673260.904	1133420.216	Shell Rot		☐
8405	12411	1673714.661	1133458.974	Heart Rot		☐
8425	1478	1673962.509	1132597.176	Shell Rot		☐
8434	12831	1669375.01	1132653.144	Top Rotten		☐
8435	12832	1669683	1132659.849	Top Rotten		☐
8436	12833	1669990.424	1132656.67	Top Rotten		☐
8437	12834	1670229.933	1132662.331	Top Rotten		☐
8439	12706	1669695.55	1134493.973	Shell Rot		☐
8447	12774	1669192.648	1134407.336	Top Rotten	CWL/CENTURY LINK FIBER	☐
8450	12702	1670241.098	1134445.814	Internal Decay		☐
8480	17412	1673887.794	1131276.92	Shell Rot		☐
8481	17413	1673796.257	1131287.157	Shell Rot		☐
8498	17120	1674398.648	1131585.129	Shell Rot		☐
8508	17100	1674303.094	1132448.446	Shell Rot	CENTURY LINK/CHARTER FIBER	☐

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
8513	202	1674316.079	1133243.862	Shell Rot	CWL/CHARTER FIBER	☐
8521	1475	1674656.109	1133292.971	Shell Rot		☐
8525	21970	1697671.192	1141713.529	Woodpecker Damage		☐
8529	21972	1697660.442	1141511.183	Internal Decay		☐
8544	28345	1697981.781	1141467.39	Top Rotten		☐
8567	17124	1675016.069	1131159.133	Internal Decay		☐
8571	17112	1675182.833	1131467.796	Top Rotten		☐
8584	21923	1696750.527	1140870.487	Heart Rot		☐
8595	21932	1696479.05	1141038.43	Internal Decay		☐
8600	17130	1676174.12	1131037.526	Heart Rot	CHARTER/CENTURY LINK FIBER	☐
8617	23802	1695885.15	1140861.18	Internal Decay		☐
8618	23803	1695924.988	1140957.648	Internal Decay		☐
8636	17089	1674902.829	1132299.099	Top Rotten		☐
8654	17070	1675027.028	1132967.15	See Remarks	SHELL ROT/ROTTEN TOP	☐
8657	17068	1675103.443	1132879.865	Shell Rot		☐
8663	17063	1675325.706	1133249.873	Heart Rot		☐
8664	10768	1700430.36	1139804.996	Top Rotten	CENTURY LINK, SOCKET, MEDIACOM FIBER	☐
8665	17062	1675215.145	1133248.04	Shell Rot		☐
8670	10991	1675829.24	1133639.052	Internal Decay		☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 1 of 5

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
8671	10770	1700740.471	1139828.026	Internal Decay	CENTURY LINK, SOCKET, MEDIACOM FIBER	☐
8672	10771	1700859.561	1139835.302	Internal Decay	CENTURY LINK, SOCKET, MEDIACOM FIBER	☐
8676	10998	1675795.412	1133464.62	Top Rotten	PRIORITY CALLED IN	☐
8678	10999	1675679.324	1133342.187	Internal Decay		☐
8696	17017	1675778.866	1132731.064	Shell Rot		☐
8713	10793	1701426.482	1140860.338	Heart Rot		☐
8731	10789	1700847.724	1141037.866	Internal Decay		☐
8746	10800	1701649.255	1141014.329	Shell Rot		☐
8748	10601	1701650.478	1141109.566	Internal Decay		☐
8752	10605	1701754.658	1141448.207	Internal Decay		☐
8772	15449	1676737.241	1133464.528	Heart Rot		☐
8776	19754	1691259.361	1130648.517	Shell Rot		☐
8779	19760	1691504.535	1130437.37	Shell Rot	TRANS LOC # MISSING	☐
8784	1067	1676838.789	1133179.178	Internal Decay		☐
8790	19779	1691096.646	1130756.587	Internal Decay		☐
8796	9524	1691195.63	1130500.653	Internal Decay		☐
8805	19746	1691175.275	1129904.306	Shell Rot	#4 & #6 TRIPLEX	☐
8809	19747	1691264.492	1129920.362	Woodpecker Damage		☐
8810	15613	1676550.071	1131001.884	Top Rotten	CHARTER/CENTURY LINK FIBER	☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 2 of 5

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
8811	19748	1691373.556	1130000.981	Shell Rot	PRIORITY REJECT CALLED IN, TRANS LOC MISSING	☐
8815	15609	1676921.522	1131128.718	Top Rotten	CWL/CHARTER/CENTURY LINK FIBER	☐
8817	9526	1691192.57	1130361.563	Internal Decay		☐
8829	15604	1676921.638	1131594.788	Internal Decay	CHARTER/CENTURY LINK FIBER	☐
8832	15603	1676923.332	1131609.233	Internal Decay		☐
8834	15602	1676918.228	1131661.593	Shell Rot		☐
8870	8012	1676905.324	1134394.983	Heart Rot		☐
8872	19767	1691865.33	1130565.368	Internal Decay	CWL, CENTURY LINK, SHO ME, & MEDIACOM FIBER	☐
8878	19765	1691974.305	1130425.227	Shell Rot	CWL, CENTURY LINK, SHO ME, & MEDIACOM FIBER	☐
8893	19763	1691979.052	1130307.713	Heart Rot		☐
8900	19789	1692142.394	1130000.314	Internal Decay	CWL, CENTURY LINK, SHO ME, & MEDIACOM FIBER	☐
8903	396	1692095.924	1129966.271	Internal Decay		☐
8905	243	1676346.013	1133819.9	Shell Rot		☐
8907	244	1676219.767	1133818.847	Shell Rot		☐
8916	10993	1675982.081	1133806.687	Shell Rot		☐
8918	1472	1675838.179	1133785.659	Shell Rot		☐
8941	409	1692598.927	1129332.017	Shell Rot	PRIORITY REJECT CALLED	☐
8942	12434	1675001.854	1133672.57	Shell Rot		☐
8950	10989	1675618.721	1133652.179	Shell Rot		☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 3 of 5

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
8957	9719	1691115.429	1131982.638	Heart Rot		☐
8971	3677	1676045.397	1134239.851	Heart Rot		☐
8984	3675	1676216.9	1134327.159	Heart Rot		☐
9003	3680	1675851.443	1134184.968	Internal Decay		☐
9004	19602	1691414.234	1132340.429	Top Rotten		☐
9021	19612	1692194.918	1132343.585	Internal Decay		☐
9031	19575	1692416.082	1132605.289	Internal Decay		☐
9052	19568	1692712.989	1132253.125	Shell Rot		☐
9062	19619	1691568.898	1132593.229	Internal Decay		☐
9063	10921	1676200.08	1135805.259	Shell Rot		☐
9064	19576	1692420.967	1132760.343	Internal Decay		☐
9068	12480	1676062.535	1135299.949	Internal Decay		☐
9083	19664	1691807.29	1132890.379	Shell Rot		☐
9090	19616	1691440.551	1132721.76	Internal Decay		☐
9104	19553	1692791.707	1132858.362	Shell Rot		☐
9125	9165	1692144.959	1133196.785	Shell Rot		☐
9127	9166	1691950.899	1133199.497	Shell Rot	#4 & #6 TRIPLEX, PRIORITY REJECT CALLED IN	☐
9137	19639	1691443.537	1133212.85	Shell Rot		☐
9166	20071	1692103.163	1133655.014	Shell Rot		☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 4 of 5

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
9181	19595	1691055.533	1132398.876	Shell Rot	CENTURY LINK, SHO ME, MEDIACOM & CHARTER	☐

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
9194	20169	1691617.011	1133703.442	Top Rotten		☐
9195	12462	1675055.497	1135270.129	Internal Decay	PRIORITY CALLED IN 2609 BRAEMORE RD	☐
9206	20171	1691759.639	1133768.011	Top Rotten		☐
9216	19448	1692396.811	1133795.491	Shell Rot		☐
9246	20161	1691080.219	1133954.614	Internal Decay	DIACOM CABLE, CWL, SHO ME, CENTURY LINK & I	☐
9257	1365	1691371.499	1134291.355	Shell Rot		☐
9263	10916	1675988.231	1136167.569	Top Rotten		☐
9272	26118	1691241.083	1134481.443	Shell Rot		☐
9278	20008	1691674.297	1134453.105	Top Rotten		☐
9285	20011	1691965.066	1134443.401	Internal Decay		☐
9288	20013	1692076.202	1134453.584	Shell Rot		☐
9292	20009	1691834.414	1134441.137	Top Rotten		☐
9304	10870	1692035.634	1134243.415	Internal Decay		☐
9306	10869	1692287.033	1134246.675	Shell Rot		☐
9315	531	1691983.149	1134782.318	Insect Damage		☐
9316	530	1691988.503	1134678.71	Heart Rot		☐
9327	20029	1691374.726	1135130.16	Shell Rot		☐
9329	20031	1691344.586	1135046.643	Internal Decay		☐
9330	20032	1691333.292	1135041.847	Internal Decay		☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 1 of 4

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
9334	20036	1691242.336	1134870.047	Internal Decay		☐
9356	28379	1675147.891	1135756.956	Top Rotten		☐
9357	19681	1690439.392	1133533.519	Internal Decay		☐
9359	19683	1690332.631	1133563.11	Internal Decay		☐
9360	12487	1675233.318	1135744.397	Shell Rot		☐
9422	19883	1690539.036	1134589.654	Top Rotten		☐
9442	19879	1691014.194	1134482.411	Heart Rot		☐
9446	19856	1690899.136	1134224.639	Heart Rot	PRIORITY REJECT CALLED IN	☐
9467	19901	1690265.994	1134298.808	Heart Rot		☐
9470	19846	1690145.972	1134294.155	Shell Rot		☐
9471	12475	1676119.088	1134987.196	Heart Rot		☐
9474	26838	1676297.742	1134831.238	Shell Rot		☐
9492	19452	1692484.352	1133541.561	Heart Rot	PRIORITY REJECT CALLED IN	☐
9501	10977	1675831.763	1134802.683	Top Rotten		☐
9505	19655	1692598.484	1133009.733	Heart Rot		☐
9508	10975	1675744.378	1134723.821	Shell Rot		☐
9511	10976	1675682.97	1134747.662	Heart Rot		☐
9512	10974	1675683.532	1134645.37	Heart Rot	PRIORITY CALLED IN 2237 CONCORDIA DR	☐
9513	19458	1692722.618	1133543.145	Internal Decay		☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 2 of 4

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
9520	19540	1693027.363	1133386.845	Shell Rot		☐
9525	19466	1693027.484	1133534.85	Woodpecker Damage		☐
9533	19537	1693260.799	1133493.621	Shell Rot		☐
9534	19536	1693371.322	1133491.652	Heart Rot		☐
9538	19533	1693569.75	1133351.588	Top Rotten		☐
9541	12437	1674777.157	1133805.048	Heart Rot		☐
9564	19500	1694159.397	1132823.299	Heart Rot		☐
9578	19518	1693936.455	1132350.336	Top Rotten		☐
9587	2411	1674436.361	1133786.332	Shell Rot		☐
9591	12428	1674344.311	1133873.924	Shell Rot		☐
9597	19471	1694005.461	1133820.311	Shell Rot		☐
9599	19473	1694152.195	1133833.779	Heart Rot		☐
9605	19478	1694583.418	1133982.052	Heart Rot		☐
9607	19485	1694453.44	1133737.38	Splits and Checks		☐
9624	19483	1694412.776	1133501.31	Top Rotten		☐
9646	8127	1694817.837	1133631.633	Shell Rot		☐
9650	19549	1693688.734	1133855.489	Internal Decay	PRIORITY REJECT CALLED IN	☐
9688	2947	1677038.776	1135084.318	Shell Rot	CWL/CENTURY LINK/CHARTER FIBER	☐
9700	9146	1692554.296	1131837.443	Internal Decay		☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 3 of 4

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
9703	9147	1692752.222	1131814.514	Shell Rot		☐
9755	7364	1694237.948	1134587.538	Heart Rot		☐
9765	7358	1694690.599	1134261.359	Shell Rot		☐
9772	15402	1677965.033	1135950.547	Shell Rot		☐
9796	15429	1677507.7	1135471.566	See Remarks	MECHANICAL DAMAGE @ ATTACHMENT POINTS	☐
9798	15408	1677652.141	1135457.737	Top Rotten		☐
9815	15417	1677519.962	1134478.428	Top Rotten	PRIORITY CALLED IN 512 W ROCK CREEK DR	☐
9825	19365	1694695.542	1131976.114	Internal Decay		☐

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
9837	19384	1695132.353	1132272.863	Heart Rot	PRIORITY REJECT CALLED IN	☐
9848	7339	1695790.498	1132083.083	Shell Rot		☐
9895	7296	1695029.069	1129638.027	Shell Rot		☐
9896	7297	1695219.559	1129570.679	Shell Rot		☐
9901	7300	1694965.177	1129284.271	Splits and Checks		☐
9926	19338	1695977.913	1130526.228	Splits and Checks		☐
9927	19339	1695919.114	1130653.062	Shell Rot		☐
9929	19340	1695805.882	1130622.93	Shell Rot		☐
9933	19304	1696219.202	1130776.98	Shell Rot		☐
9942	19295	1697019.32	1130634.592	Shell Rot		☐
9945	19285	1696439.731	1129929.754	Splits and Checks		☐
9967	19262	1697135.678	1130304.518	Top Rotten	DM & CHARTER CABLE, MEDIACOM & CENTURY L	☐
9978	19188	1697628.278	1129501.918	Shell Rot		☐
10025	4113	1697992.691	1139297.731	Heart Rot		☐
10077	5408	1695198.026	1139727.101	Shell Rot	TRANS LOC MISSING	☐
10089	629	1696764.556	1139498.652	Heart Rot		☐
10103	10719	1694398.226	1139903.713	Shell Rot		☐
10106	4128	1694056.067	1139922.133	Shell Rot		☐
10110	10720	1694945.749	1139799.54	Internal Decay	SAID OWNER OF TOM'S IMPORTS HAS KEY TO L	☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 1 of 4

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
10139	9864	1687477.955	1133989.683	Shell Rot	CHARTER SOCKET & CENTURY LINK FIBER	☐
10143	9867	1687449.894	1133437.415	Shell Rot	CHARTER & CENTURY LINK FIBER	☐
10167	13765	1686930.025	1132361.979	Top Rotten		☐
10168	13766	1686937.72	1132325.604	Shell Rot		☐
10179	15280	1677970.979	1134472.412	Shell Rot		☐
10188	15444	1677600.082	1134028.904	Shell Rot		☐
10190	15442	1677619.762	1133662.907	Shell Rot	PRIORITY CALLED IN 703 E ROCK CREEK DR	☐
10193	15466	1677358.108	1133534.724	Shell Rot		☐
10194	15440	1677320.073	1133670.389	Pole broken at groun	PRIORITY CALLED IN 702 SEYMOUR RD	☐
10200	15269	1678299.775	1136038.39	Internal Decay		☐
10202	15266	1678286.778	1135810.652	Heart Rot		☐
10203	15265	1678285.346	1135679.917	Heart Rot	PRIORITY CALLED IN 15 SAPPINGTON DRIVE	☐
10204	15264	1678281.411	1135575.46	Shell Rot		☐
10215	15253	1678260.574	1134422.396	Top Rotten		☐
10216	15252	1678257.778	1134214.578	Shell Rot		☐
10218	15249	1678252.716	1133881.559	Internal Decay		☐
10219	15251	1678114.728	1134000.641	Shell Rot		☐
10223	15223	1678549.414	1133607.292	Heart Rot		☐
10224	15222	1678731.71	1133818.824	Shell Rot		☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 2 of 4

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
10237	15195	1678803.136	1135945.674	Heart Rot	PRIORITY CALLED IN 4 RUSSEL BLVD	☐
10240	15199	1678790.16	1135644.361	Heart Rot		☐
10241	16200	1678793.832	1135493.423	Internal Decay		☐
10261	15231	1679235.62	1134003.679	Splits and Checks		☐
10263	15229	1679206.604	1133763.976	Shell Rot		☐
10264	15228	1679049.236	1133786.012	Top Rotten		☐
10273	15245	1678087.277	1133584.861	Shell Rot		☐
10297	15187	1679130.155	1135684.847	Heart Rot		☐
10307	15192	1679287.478	1135907.884	Shell Rot	CENTURY LINK/SOCKET FIBER	☐
10311	15581	1677807.214	1130942.547	Internal Decay	PRIORITY CALLED IN/CENTURY LINK/CHARTER FIBER	☐
10312	15580	1677905.449	1131017.154	Shell Rot		☐
10317	15586	1677474.509	1131193.343	Shell Rot		☐
10323	2936	1677026.301	1132806.306	Heart Rot	CENTURY LINK/CHARTER/CWL FIBER	☐
10324	2937	1677021.159	1133007.438	Heart Rot	CENTURY LINK/CHARTER/CWL FIBER	☐
10326	15450	1677031.793	1133404.82	Shell Rot	CENTURY LINK/CHARTER/CWL FIBER	☐
10330	2935	1677024.099	1132608.369	Shell Rot	CENTURY LINK/CHARTER/CWL FIBER	☐
10365	15510	1678068.025	1131623.716	Shell Rot		☐
10381	15540	1678106.343	1133368.16	Shell Rot		☐
10387	15531	1677576.715	1133356.89	Shell Rot	PRIORITY CALLED IN 804 COLGATE	☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 3 of 4

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
10398	15574	1677948.89	1131180.737	Shell Rot		☐
10421	2409	1678841.026	1133046.639	Shell Rot	CALLED IN EAST SIDE OF RUSSEL ELEMENTARY	☐
10427	15566	1678791.572	1131353.332	Shell Rot	PRIORITY CALLED IN 1704 OXFORD DR	☐
10442	8331	1678228.212	1130972.543	Internal Decay		☐
10450	14884	1679351.904	1130626.631	Top Rotten	CENTURY LINK/CHARTER FIBER	☐

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
10469	1327	1686928.068	1132186.407	Shell Rot		☐
10474	9253	1687596.604	1134113.79	Shell Rot	PRIORITY REJECT CALLED IN	☐
10476	10197	1679387.292	1131873.451	Heart Rot	PRIORITY CALLED IN 1604 PRINCETON DR	☐
10490	7470	1678460.558	1132057.459	Top Rotten		☐
10495	238	1688165.462	1132118.66	Shell Rot		☐
10506	10171	1679527.598	1131501.926	Shell Rot		☐
10514	1742	1688513.625	1131080.41	Shell Rot		☐
10528	3579	1688180.129	1131189.952	Shell Rot		☐
10531	9813	1688731.74	1131916.7	Shell Rot	MEDIACOM & CHARTER CABLE	☐
10533	8243	1679331.101	1131720.067	Top Rotten		☐
10547	9803	1688607.217	1131099.253	Heart Rot		☐
10556	13746	1687405.743	1132217.027	Shell Rot		☐
10576	15028	1679738.859	1132363.529	Internal Decay		☐
10608	19247	1697441.162	1129818.624	Shell Rot		☐
10611	19248	1697487.66	1129799.979	Shell Rot		☐
10634	19233	1698264.29	1130526.748	Shell Rot		☐
10663	19318	1697477.283	1131482.218	Top Rotten		☐
10696	215	1698342.561	1133385.944	Internal Decay	PRIORITY REJECT CALLED IN	☐
10708	19395	1697973.331	1133263.717	Heart Rot	PRIORITY REJECT CALLED IN	☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 1 of 2

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
10726	1398	1688972.123	1135107.447	Internal Decay		☐
10727	2085	1689258.964	1134687.553	Heart Rot		☐
10728	2084	1689262.929	1134763.368	Shell Rot		☐
10753	4867	1686962.001	1133316.281	Internal Decay		☐
10754	14957	1680511.547	1132539.467	Top Rotten		☐
10755	13768	1686925.617	1133245.719	Internal Decay		☐
10759	227	1680423.137	1132167.142	Top Rotten		☐
10781	3510	1686576.038	1133614.581	Heart Rot	DM & CENTURY LINK FIBER, MEDIACOM & CHARTER	☐
10786	14979	1681163.011	1131888.984	Shell Rot		☐
10856	13785	1685796.221	1134722.386	Heart Rot		☐
10918	9066	1685914.959	1133135.417	Top Rotten		☐

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
10960	14992	1680496.415	1132988.067	Shell Rot		☐
10969	15001	1680824.419	1133426.061	Shell Rot		☐
11009	14701	1681993.818	1134104.843	Shell Rot		☐
11010	14700	1681919.597	1134106.583	Heart Rot		☐
11037	14667	1681266.194	1134868.795	Heart Rot	TW/JM	☐
11042	13860	1685395.014	1132832.662	Internal Decay	PRIORITY REJECT CALLED IN	☐
11046	14670	1681140.977	1135138.194	Heart Rot		☐
11048	14672	1681282.429	1135227.91	Shell Rot		☐
11054	13865	1685487.135	1133453.833	Heart Rot		☐
11056	13870	1685486.945	1133545.203	Internal Decay		☐
11065	15109	1680906.092	1133922.149	Shell Rot	PRIORITY CALLED IN 502 SPRING VALLEY RD	☐
11072	15105	1680879.09	1134126.254	Shell Rot	PRIORITY CALLED IN 409 SPRING VALLEY RD	☐
11073	9070	1685933.747	1133651.388	Top Rotten		☐
11074	15104	1680879.014	1134302.449	Shell Rot		☐
11079	14687	1681069.96	1134188.146	Shell Rot		☐
11090	15101	1680844.641	1134353.673	Heart Rot	#4 ACSR	☐
11094	13872	1685053.132	1133615.738	Shell Rot		☐
11096	13874	1685046.509	1133279.496	Internal Decay		☐
11107	3418	1684827.156	1133864.635	Internal Decay		☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 1 of 4

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
11109	14678	1680838.462	1134948.518	Shell Rot		☐
11112	14675	1680925.079	1135248.813	Heart Rot		☐
11119	15108	1680679.811	1133690.873	Internal Decay	#4 ACSR, 1/0 TRIPLEX, #2 TRIPLEX	☐
11124	3417	1684823.309	1133909.655	Internal Decay		☐
11136	9981	1685024.174	1134609.386	Shell Rot		☐
11139	15120	1680407.057	1134081.607	Heart Rot		☐
11145	15121	1680444.675	1134311.281	Top Rotten		☐
11149	9966	1685044.641	1134982.544	Shell Rot		☐
11151	9965	1685037.221	1134885.949	Shell Rot		☐
11161	15137	1680271.328	1134542.259	Heart Rot		☐
11168	10647	1685275.499	1135303.854	Shell Rot		☐
11174	15142	1680278.791	1135013.487	Woodpecker Damage		☐
11179	15130	1680514.463	1135178.439	Heart Rot		☐
11182	13713	1686687.479	1131988.668	Shell Rot		☐
11183	13712	1686480.356	1131955.951	Shell Rot		☐
11185	8630	1686384.394	1131771.091	Shell Rot		☐
11186	15132	1680529.743	1134749.337	Heart Rot		☐
11193	15146	1680284.225	1135324.904	Heart Rot		☐
11195	15148	1680289.993	1135550.731	Top Rotten		☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 2 of 4

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
11201	13705	1685335.884	1131833.746	Heart Rot		☐
11203	13679	1685037.062	1131773.275	Shell Rot		☐
11204	13680	1685058.756	1131741.151	Shell Rot		☐
11206	13714	1686879.134	1131815.299	Shell Rot		☐
11209	13685	1685124.76	1131362.08	Shell Rot		☐
11213	13676	1684724.477	1131399.558	Shell Rot		☐
11214	13675	1684444.321	1131171.709	Shell Rot		☐
11234	13737	1685712.297	1131418.526	Shell Rot		☐
11242	13730	1686223.119	1131488.289	Shell Rot		☐
11250	14641	1682061.233	1135595.575	Shell Rot		☐
11253	7805	1686488.491	1131672.97	Heart Rot	STOMER WANTS TO BE CONTACTED BEFORE PC	☐
11261	14809	1682135.775	1132798.209	Shell Rot		☐
11278	14938	1681848.278	1132845.692	Top Rotten	PRIORITY CALLED IN 806 ROLLINS RD	☐
11279	13742	1686562.08	1131294.701	Shell Rot		☐
11281	13744	1686342.86	1131241.977	Shell Rot		☐
11284	13692	1685404.029	1131047.066	Top Rotten		☐
11285	26114493	1685428.926	1130995.46	Heart Rot	CALLLED IN, POLE NUMBER REPORTED IS METE	☐
11288	13690	1685237.68	1130674.389	Shell Rot		☐
11297	13697	1685692.914	1131064.918	Shell Rot		☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 3 of 4

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
11309	13694	1685989.373	1131026.166	Shell Rot		☐
11312	14946	1681425.022	1132851.036	Shell Rot		☐
11314	14945	1681411.984	1132762.395	Top Rotten		☐
11319	13621	1686413.835	1130949.598	Heart Rot		☐
11320	14802	1682194.3	1132112.704	Shell Rot		☐

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
11339	13639	1687097.56	1130567.985	Shell Rot		☐
11345	14912	1681609.219	1131396.274	Top Rotten		☐
11352	14914	1681803.726	1131608.432	Heart Rot		☐
11353	14915	1681706.638	1131651.087	Internal Decay		☐
11355	10219	1681964.866	1131590.518	Top Rotten		☐
11360	13648	1686489.824	1130461.012	Internal Decay		☐
11361	10218	1682054.525	1131574.038	Shell Rot		☐
11393	10214	1681878.987	1131045.734	Top Rotten		☐
11395	10216	1681981.882	1131338.665	Shell Rot	CHARTER/CENTURY LINK FIBER	☐
11456	12895	1666452.213	1130594.438	Woodpecker Damage		☐
11463	12892	1666646.185	1130385.928	Woodpecker Damage		☐
11471	12887	1667378.519	1130297.521	Top Rotten	2ND SWITCH #6784Y	☐
11484	12884	1668069.113	1130215.235	Top Rotten		☐
11489	12882	1668515.139	1130160.112	Top Rotten		☐
11492	12881	1668758.046	1130134.018	Top Rotten		☐
11518	13919	1683643.727	1133259.987	Internal Decay		☐
11521	13235	1668870.326	1129811.16	Internal Decay		☐
11542	1766	1668155.073	1127736.011	Internal Decay		☐
11614	13004	1683424.193	1134781.027	Heart Rot	PRIORITY REJECT CALLED IN	☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 1 of 4

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
11632	13284	1666738.65	1126792.851	Internal Decay		☐
11634	13283	1666954.319	1126771.291	Top Rotten		☐
11636	13282	1667166.661	1126744.423	Top Rotten		☐
11644	13277	1667729.072	1126672.316	Shell Rot		☐
11649	13279	1668205.13	1126608.399	Shell Rot		☐
11718	13297	1666304.871	1126441.363	Top Rotten		☐
11720	13298	1666298.829	1126234.262	Top Rotten		☐
11722	13299	1666294.094	1126022.979	Top Rotten		☐
11731	14754	1682849.935	1132852.104	Heart Rot		☐
11742	14738	1682255.262	1133092.161	Heart Rot	LED IN (708 WEST BLVD), CHARTER MEDIACOM &	☐
11751	14746	1682257.189	1133654.181	Shell Rot	CHARTER MEDIACOM & CENTURY LINK FIBER	☐
11759	14749	1682253.657	1133955.842	Heart Rot	LED IN (408 WEST BLVD) CHARTER MEDIACOM &	☐
11768	12988	1671579.446	1126484.159	Shell Rot		☐
11786	14831	1683963.321	1132335.718	Shell Rot		☐
11797	12976	1671607.588	1128083.931	Top Rotten		☐
11798	12977	1671611.78	1128260.716	Top Rotten		☐
11804	17581	1671642.647	1131289.993	Heart Rot	PRIORITY CALLED IN 1201 CUNNINGHAM RD	☐
11812	17583	1671635.976	1130905.565	Top Rotten		☐
11826	14874	1684645.302	1132478.077	Shell Rot		☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 2 of 4

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
11827	14875	1684738.148	1132536.524	Heart Rot	Y REJECT CALLED IN (805 EDGEWOOD), #4 & #6	☐
11829	14877	1684875.244	1132626.786	Internal Decay		☐
11837	17590	1671618.575	1130124.763	Shell Rot	2ND SWITCH #7107	☐
11838	17591	1671619.305	1130066.962	Heart Rot		☐
11862	14859	1683900.15	1131769.955	Heart Rot	PRIORITY REJECT CALLED IN (1008 LAKESHORE D	☐
11888	11895	1669332.791	1129538.372	Shell Rot		☐
11889	14808	1682254.035	1132785.766	Shell Rot	CENTURY LINK & MEDIACOM FIBER	☐
11914	14772	1682915.271	1132741.188	Heart Rot		☐
11936	17564	1673371.542	1131064.012	Heart Rot		☐
11937	14787	1682817.239	1131619.428	Shell Rot		☐
11938	17565	1673377.714	1130960.792	Shell Rot		☐
11939	17566	1673380.352	1130879.696	Shell Rot		☐
11954	17556	1673322.162	1130562.82	Internal Decay		☐
11956	17557	1673340.917	1130648.128	Top Rotten		☐
11962	14823	1683135.21	1131221.15	Internal Decay		☐
11963	14821	1682821.72	1131209.296	Shell Rot		☐
11979	17448	1673786.822	1130563.343	Internal Decay		☐
12011	17440	1674085.018	1129961.012	Internal Decay		☐
12042	12932	1672642.799	1129061.571	Internal Decay		☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 3 of 4

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
12044	4034	1672411.48	1128937.157	Shell Rot		☐

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
12076	5277	1694910.734	1140954.62	Shell Rot		☐
12078	1493	1694967.129	1140935.236	Shell Rot		☐
12081	1937	1694273.793	1127772.205	Shell Rot		☐
12085	19348	1694168.553	1127895.293	Shell Rot		☐
12090	5419	1693756.057	1128225.769	Shell Rot	PRIORITY REJECT CALLED IN	☐
12096	21666	1695874.196	1140548.922	Internal Decay		☐
12099	5284	1695349.277	1140601.199	Shell Rot		☐
12102	5282	1695048.296	1140677.175	Shell Rot		☐
12117	19099	1693226.347	1127655.259	Top Rotten		☐
12121	19098	1693306.672	1127523.222	Internal Decay		☐
12127	19102	1693039.039	1127590.117	Heart Rot	PRIORITY REJECT CALLED IN	☐
12140	9218	1693842.833	1139914.286	Internal Decay		☐
12145	9213	1693527.174	1139959.94	Shell Rot		☐
12281	19819	1690413.789	1128874.887	Shell Rot		☐
12282	1073	1668593.165	1115339.669	Top Rotten		☐
12290	18637	1667335.513	1111434.627	Top Rotten		☐
12293	19812	1690870.532	1128011.322	Shell Rot		☐
12310	19813	1690673.318	1128618.121	Shell Rot		☐
12333	18651	1663715.066	1109995.103	Shell Rot		☐

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
12374	13558	1687435.581	1123893.642	Shell Rot		☐
12383	13547	1687918.253	1123564.057	Shell Rot		☐
12388	13549	1687547.976	1123625.526	Heart Rot		☐
12394	13598	1686107.141	1127201.867	Shell Rot	CWL, CWL CENTURY LINK & UNKNOWN FIBER	☐
12414	2217	1686440.336	1128145.3	Shell Rot	CWL, MEDIACOM & CENTURY LINK FIBER	☐
12420	18688	1658775.513	1111370.61	Heart Rot		☐
12423	2218	1686301.893	1128189.917	Shell Rot		☐
12424	2219	1686162.192	1128232.507	Shell Rot		☐
12425	2220	1686102.765	1128284.364	Shell Rot		☐
12429	2223	1686402.273	1128292.869	Shell Rot		☐
12437	13611	1686627.502	1128862.438	Shell Rot	CWL, CENTURY LINK & MEDIACOM FIBER	☐
12439	13613	1686672.356	1129031.073	Shell Rot		☐
12475	18801	1655993.034	1111502.273	Internal Decay		☐
12496	10813	1686152.722	1125044.504	Shell Rot	CWL, CENTURY LINK & MEDIACOM FIBER	☐
12508	18811	1654318.017	1111755.865	Shell Rot		☐
12511	18812	1653965.798	1111732.405	Internal Decay	H FRAME CONSTRUCTION WITH BOONE	☐
12518	18815	1653311.953	1111739.8	Internal Decay		☐
12550	1951	1698419.861	1120747.397	Internal Decay		☐
12571	2343	1697495.597	1121107.347	Shell Rot		☐

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
12578	16893	1698098.862	1120565.414	Heart Rot		☐
12583	16872	1698300.157	1119683.548	Shell Rot		☐
12589	16883	1698106.019	1119608.246	Heart Rot	SOCKET & CENTURY LINK FIBER	☐

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
12645	28205	1698488.616	1119182.002	Shell Rot	SOCKET, MEDIACOM, CHARTER & CENTURY LINK	☐
12654	16772	1694837.645	1119533.885	Shell Rot		☐
12664	1996	1694660.028	1119240.147	Shell Rot		☐
12671	16675	1693498.479	1119314.659	Shell Rot	CWL, MEDIACOM & CENTURY LINK FIBER	☐
12687	16690	1693497.725	1119397.635	Internal Decay	PRIORITY REJECT CALLED IN	☐
12691	16692	1693525.839	1120105.187	Shell Rot		☐
12692	16693	1693523.123	1120384.904	Shell Rot		☐
12700	18819	1651900.257	1111258.806	Internal Decay		☐
12704	18821	1651479.829	1111134.704	Shell Rot		☐
12719	16668	1692369.309	1119320.826	Shell Rot	CWL, MEDIACOM, & CENTURY LINK FIBER	☐
12734	18826	1650057.306	1111716.044	Shell Rot		☐
12736	18828	1649614.932	1111956.862	Top Rotten		☐
12758	18841	1651722.417	1109422.996	Shell Rot		☐
12766	18846	1651700.033	1107975.82	Shell Rot		☐
12808	2235	1686021.199	1123678.811	Shell Rot		☐
12813	2238	1686096.061	1123391.755	Shell Rot		☐
12826	2233	1686626.93	1123598.459	Shell Rot	PRIORITY REJECT CALLED IN	☐
12838	2228	1687007.674	1123589.366	Shell Rot		☐
12842	18898	1655826.432	1103705.989	Internal Decay	8A CWC	☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 1 of 3

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
12844	18899	1656211.542	1103708.573	Internal Decay	8A CWC	☐
12859	17807	1656869.553	1102190.315	Splits and Checks	8A CWC	☐
12887	734	1687115.154	1122523	Shell Rot	PRIORITY REJECT CALLED IN, CWL & MEDIACOM FIBER	☐
12893	728	1685963.641	1122603.716	Shell Rot	CWL & MEDIACOM FIBER	☐
12929	15950	1685989.37	1121893.879	Internal Decay		☐
12953	15933	1685053.971	1121969.149	Shell Rot	PRIORITY REJECT CALLED IN, (301 EL CORTEZ DR)	☐
12975	13357	1674606.586	1120538.136	Heart Rot		☐
13017	15978	1685473.669	1122716.203	Shell Rot		☐
13049	9311	1687899.289	1121729.397	Shell Rot		☐
13066	15910	1676772.744	1123589.114	Woodpecker Damage		☐
13073	26010	1676210.774	1123263.324	Woodpecker Damage		☐
13075	26011	1676010.708	1123286.204	Woodpecker Damage		☐
13079	16039	1685286.784	1121653.86	Internal Decay	PRIORITY REJECT CALLED IN	☐
13085	16031	1684900.849	1121115.78	Internal Decay		☐
13088	16047	1685153.425	1120969.616	Heart Rot	PRIORITY REJECT CALLED IN (3604 SIERRA MADRA)	☐
13097	15831	1677334.013	1125298.028	Heart Rot		☐
13118	16080	1686107.961	1121529.656	Shell Rot		☐
13121	16078	1686308.968	1121537.534	Heart Rot		☐
13142	13531	1686128.809	1120861.474	Shell Rot	CWL & CENTURY LINK FIBER	☐

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
13157	94	1676595.169	1126588.916	Heart Rot	PRIORITY 2401 HILLSHIRE DR	☐
13179	16094	1685582.752	1120711.667	Shell Rot		☐
13249	18727	1675291.496	1129601.725	Shell Rot		☐
13273	18763	1675395.834	1130237.085	Shell Rot		☐
13275	10007	1685499.537	1126835.195	Heart Rot		☐
13291	18738	1675832.372	1129822.586	Top Rotten	CENTURY LINK/SOCKET FIBER	☐
13294	18741	1675959.995	1129779.251	Shell Rot	CENTURY LINK/SOCKET FIBER	☐
13295	18742	1676045.396	1129750.972	Shell Rot		☐
13298	10019	1684736.862	1126273.78	Shell Rot		☐
13299	10017	1684734.248	1126146.472	Shell Rot		☐

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
13361	1863	1676060.131	1130326.151	Shell Rot	PRIORITY 2313 WOODRIDGE RD	☐
13363	18439	1676226.872	1130474.646	Shell Rot		☐
13373	877	1686392.751	1121258.948	Top Rotten		☐
13381	18438	1676366.046	1130333.159	Shell Rot		☐
13392	16025	1684719.219	1121686.207	Shell Rot		☐
13393	16026	1684712.805	1121552.867	Shell Rot		☐
13405	705	1684646.733	1120386.34	Heart Rot	CWL, MEDIACOM, & CENTURY LINK FIBER	☐
13406	704	1684645.518	1120226.201	Shell Rot	CWL & MEDIACOM FIBER	☐
13408	702	1684638.109	1119896.177	Shell Rot		☐
13410	1300	1684642.277	1119569.316	Internal Decay	PRIORITY REJECT CALLED IN, CWL & MEDIACOM FIBER	☐
13426	2012	1689184.03	1119442.512	Shell Rot		☐
13435	15620	1676892.307	1130192.373	Heart Rot	CWL/CENTURY LINK/SOCKET FIBER	☐
13449	13509	1687221.264	1120557.235	Shell Rot	CWL & MEDIACOM FIBER	☐
13471	1293	1687163.918	1117803.061	Shell Rot		☐
13500	16645	1689052.235	1118678.023	Top Rotten		☐
13509	2286	1688243.392	1118902.601	Top Split Out		☐
13510	2285	1688270.865	1118887.942	Shell Rot	TRANS LOC MISSING	☐
13543	3947	1684607.489	1119294.169	Heart Rot	PRIORITY REJECT CALLED IN, CWL & MEDIACOM FIBER	☐
13545	394	1684557.242	1119296.557	Shell Rot		☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 1 of 4

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
13551	3952	1684584.537	1118354.649	Shell Rot	CWL MEDIACOM CHARTER & CENTURY LINK FIBER	☐
13552	3953	1684580.093	1118158.885	Shell Rot	CWL MEDIACOM CHARTER & CENTURY LINK FIBER	☐
13554	3955	1684575.841	1117848.015	Shell Rot	CWL MEDIACOM CHARTER & CENTURY LINK FIBER	☐
13555	16131	1684575.486	1117730.136	Shell Rot	CWL MEDIACOM CHARTER & CENTURY LINK FIBER	☐
13576	16192	1684504.53	1114190.777	Heart Rot		☐
13586	15996	1683960.078	1122562.479	Shell Rot		☐
13592	16000	1683805.717	1123199.437	Shell Rot		☐
13604	7636	1683613.699	1122771.429	Shell Rot		☐
13606	7637	1683608.835	1122629.672	Shell Rot		☐
13607	7638	1683607.968	1122579.314	Shell Rot		☐
13609	16016	1683776.048	1122230.951	Shell Rot	CENTURY LINK & MEDIACOM FIBER	☐
13638	12319	1682631.735	1121068.423	Internal Decay		☐
13639	12320	1682627.409	1120891.661	Shell Rot		☐
13641	12322	1682646.394	1120508.894	Shell Rot		☐
13643	12324	1682630.835	1120134.428	Heart Rot		☐
13645	3939	1682630.285	1119786.965	Shell Rot		☐
13659	15633	1677095.114	1130517.113	Internal Decay		☐
13675	15644	1677447.504	1130454.673	Shell Rot		☐
13736	15693	1678563.667	1129875.761	Shell Rot	CWL/CENTURY LINK FIBER	☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 2 of 4

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
13750	10111	1677960.693	1130198.404	Pole broken at groun	PRIORITY CALLED IN 1901 RIDGEMONT DR	☐
13753	10256	1682621.84	1124816.401	Shell Rot		☐
13756	10260	1682659.518	1124535.133	Top Rotten		☐
13779	9485	1683307.8	1123704.707	Internal Decay	MEDIACOM & CENTURY LINK FIBER	☐
13790	9486	1683351.607	1123497.513	Shell Rot		☐
13793	26185	1683292.502	1123258.254	Shell Rot		☐
13794	9497	1683274.469	1123088.944	Heart Rot	PRIORITY REJECT CALLED IN (3103	☐
13795	15685	1678455.303	1129709.337	Shell Rot		☐
13799	9201	1683165.022	1122943.325	Internal Decay	PRIORITY REJECT CALLED IN	☐
13809	9487	1683258.829	1123522.283	Heart Rot		☐
13812	15679	1678554.317	1129386.034	Top Rotten		☐
13819	9474	1682853.066	1123367.216	Heart Rot		☐
13825	9478	1682397.445	1123447.879	Heart Rot		☐
13827	9467	1682714.133	1123015.988	Heart Rot		☐
13828	9469	1682873.438	1122994.051	Heart Rot		☐
13835	9472	1682868.076	1123154.814	Heart Rot		☐
13837	9461	1682881.295	1122827.184	Internal Decay		☐
13848	9439	1682865.458	1122170.565	Shell Rot		☐
13858	10245	1684890.888	1124644.425	Shell Rot		☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 3 of 4

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
13863	10250	1683801.699	1124755.131	Heart Rot		☐
13881	10293	1680041.77	1124595.007	Shell Rot		☐
13883	10297	1679817.537	1125215.745	Shell Rot	CWL & CENTURY LINK FIBER	☐
13889	9402	1679555.307	1124904.023	Shell Rot		☐
13895	10296	1680201.59	1124283.672	Shell Rot		☐
13901	786	1683875.265	1119495.962	Shell Rot		☐
13904	783	1683287.92	1119573.68	Shell Rot		☐
13905	782	1683145.51	1119611.647	Shell Rot		☐
13913	775	1682002.608	1119807.026	Shell Rot	CWL & MEDIACOM FIBER	☐
13916	772	1681427.234	1119860.289	Shell Rot	CWL, MEDIACOM, SOCKET & CENTURY LINK FIBER	☐
13918	770	1681041.917	1119895.457	Internal Decay	CWL, MEDIACOM, SOCKET & CENTURY LINK FIBER	☐
13922	766	1680275.273	1119957.447	Shell Rot	CWL MEDIACOM & CENTURY LINK FIBER	☐
13938	11338	1690628.313	1115889.384	Woodpecker Damage		☐

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
13942	15733	1679568.96	1129647.257	Shell Rot		☐
13960	15700	1678844.942	1129667.95	Heart Rot		☐
13974	15698	1679024.821	1129619.977	Shell Rot		☐
13975	15730	1679017.485	1129261.773	Shell Rot		☐
13992	15729	1679149.251	1129346.441	Shell Rot		☐
13997	15697	1679153.384	1129613.972	Heart Rot	#2 TRIPLEX/#6 DUPLEX	☐
14008	15751	1679438.721	1129429.783	Shell Rot	#2 TRIPLEX/#6 DUPLEX	☐
14010	15736	1679610.926	1129481.426	Heart Rot		☐
14014	15739	1679705.801	1129373.847	Internal Decay		☐
14031	16195	1681847.383	1114954.491	Shell Rot	NK MEDIACOM & SOCKET FIBER, PRIORITY REJECT	☐
14038	3916	1681071.758	1117065.551	Shell Rot		☐
14047	1674	1678722.103	1140436.591	Shell Rot		☐
14048	1675	1678715.123	1140300.312	Internal Decay		☐
14074	15743	1679775.226	1129017.688	Pole broken at groun	PRIORITY CALLED IN 1512 MILLS DR	☐
14080	3923	1679676.875	1117318.379	Shell Rot		☐
14084	10080	1679549.539	1129915.214	Internal Decay		☐
14091	16165	1681896.508	1117527.857	Shell Rot	SOCKET & CENTURY LINK FIBER	☐
14092	16166	1681894.095	1117739.755	Shell Rot	SOCKET & CENTURY LINK FIBER	☐
14097	16168	1681900.863	1118171.842	Lightning Strike	SOCKET & CENTURY LINK FIBER	☐

REPORT BY LEE INSPECTION AND CONSULTING SERVICES, INC.

Page 1 of 2

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
14101	10095	1679771.164	1130148.378	Heart Rot		☐
14108	10097	1679462.451	1130171.349	Pole broken at groun	PRIORITY CALLED IN 1624 HIGHRIDGE CIR	☐
14124	16211	1679293.824	1118049.887	Heart Rot	CENTURY LINK & MEDIACOM FIBER	☐
14126	10093	1679967.64	1130073.614	Shell Rot		☐
14130	16561	1679263.936	1116856.658	Shell Rot		☐
14137	16567	1679245.8	1115454.838	Shell Rot		☐
14152	10115	1680121.102	1130369.611	Heart Rot		☐
14182	16605	1677769.463	1112622.569	Heart Rot	PRIORITY REJECT CALLED IN	☐
14191	15851	1681492.907	1130461.362	Internal Decay		☐
14203	16613	1677940.023	1111128.005	Woodpecker Damage		☐
14204	16614	1678109.448	1111126.627	Woodpecker Damage		☐
14213	16621	1679649.041	1111105.896	Heart Rot		☐
14214	16622	1679855.245	1111110.29	Shell Rot		☐
14218	16624	1680266.92	1111121.637	Internal Decay	PRIORITY REJECT CALLED IN 1309 GLASGLOW DR	☐
14227	9579	1680928.436	1111117.572	Top Rotten		☐
14229	9580	1680963.741	1111135.064	Heart Rot		☐
14260	15855	1681564.817	1130237.061	Shell Rot		☐

COLUMBIA WATER AND LIGHT REJECT SUMMARY REPORT

<i>EntryNumber:</i>	<i>POLE_NUM:</i>	<i>Easting:</i>	<i>Northing:</i>	<i>Reject Reason</i>	<i>Remarks:</i>	<i>Work Completed</i>
14336	14394	1683199.827	1142823.416	Top Split Out		☐
14341	2317	1708388.266	1160577.969	Shell Rot		☐
14352	20663	1699502.205	1136498.382	Top Rotten		☐
14367	3594	1700020.766	1137913.997	Internal Decay	CWL MEDIACOM & CENTURY LINK FIBER	☐
14368	3593	1700073.371	1137912.411	Shell Rot	CWL MEDIACOM & CENTURY LINK FIBER	☐
14369	3592	1700124.923	1137906.757	Heart Rot	T CALLED IN (801 KEENE), CWL MEDIACOM & CEN	☐
14372	20667	1699902.21	1137207.519	Top Rotten	CWL & CENTURY LINK FIBER	☐
14382	5374	1697099.818	1138778.544	Shell Rot		☐
14388	11068	1669272.49	1135454.997	Top Rotten		☐
14401	11097	1670041.265	1134602.378	Internal Decay		☐
14415	24863	1673814.149	1133633.283	Heart Rot		☐
14417	12420	1673742.049	1133734.034	Shell Rot		☐
14418	12425	1673750.846	1133880.723	Shell Rot		☐
14436	4333	1692506.78	1139283.268	Shell Rot	SOME SHELL ROT	☐
14438	4336	1692536.775	1139460.219	Internal Decay		☐
14457	4349	1692815.196	1139568.718	Shell Rot		☐