
Presentation to the Downtown Leadership Council


Issues with Infrastructure

- * Capacity for development
- * Capacity due to Condition(aging infrastructure)


Development Projects



Sewer Capacity Analysis




Proposed Projects




Downtown Leadership Council Study Area

Primary and Overlay Zoning Districts





City of Columbia


Drainage Area for Flatbranch that includes Downtown



Sources of Inflow & Infiltration








Sewer Tap







Consultant for Study



Flat Branch Flow Monitoring

City of Columbia, Missouri


April 2-3, 2014 Rainfall Events

Site 3 - 3A132 (21")


Site 4 - 3A106 (18")

Site 5 - 3A108 (15")


Current Manholes Flow Monitored




Drainage Area for Flatbranch that includes Downtown




Percent Capacity of Sewer System during Wet Weather



Total Flow for Flatbranch that includes Downtown



Sources of Inflow & Infiltration



Stormwater Box Culvert



Stormwater Box Culvert



Garth Street near Sexton Road




Photo taken 13 years ago.



Existing Condition

- We have newer technology that we camera our stormwater and sewer system but not all the system has been completed
- * We are finding infrastructure we did not know existed (PCC we thought were abandoned, water lines, stormwater)
- Different types of pipe(brick, stone, wood, clay, PVC, Orangeburg)
- * Newest sewer main was built in 1950's that serves Flatbranch

Staff Questions for the DLC

- * What type of growth should staff plan for Downtown?
- * How much of each?
 - * Residential
 - * Office
 - * Retail
 - * Industrial