

APPLICATION STRUCTR PERMIT PROPERTY ADDRESS

County Parcel Number
 INSPECTION

Old Account Number
 RESULT DATE/STATUS

INSPECTOR

12	00002067	2405 GRAND BANKS DR	17-106-00-10-020.00-01	7/30/13	DISAPPROVED	DSV
	000 000	ERO 00 EROSION CONTROL	ERI0 0004 EROSION CONTROL			
		RES COMM: house locked...no lockbox as instructed				
12	00002996	3632 ASPEN HEIGHTS PKWY APT 100	17-702-00-14-001.00-01	7/09/13	DISAPPROVED	DRB
	000 000	ERO 00 EROSION CONTROL	ERI0 0004 EROSION CONTROL			
		RES COMM: 1-extend fire wall to exterior wall at upstairs bedroom				
		RES COMM: north side				
12	00002997	3632 ASPEN HEIGHTS PKWY APT 101	17-702-00-14-001.00-01	7/09/13	DISAPPROVED	DRB
	000 000	ERO 00 EROSION CONTROL	ERI0 0004 EROSION CONTROL			
		RES COMM: 1-extend fire wall to exterior wall at upstairs bedroom				
		RES COMM: north side				
12	00003037	3635 ASPEN HEIGHTS PKWY	17-702-00-14-001.00-01	7/15/13	DISAPPROVED	DRB
	000 000	ERO 00 EROSION CONTROL	ERI0 0004 EROSION CONTROL			
		RES COMM: 1-Need tempered windows at required location can check at				
		RES COMM: final				
12	00003120	3636 ASPEN HEIGHTS PKWY APT 100	17-702-00-14-001.00-01	7/09/13	DISAPPROVED	DRB
	000 000	ERO 00 EROSION CONTROL	ERI0 0004 EROSION CONTROL			
		RES COMM: 1-Need lateral bracing at proper locations for roof trusses				
12	00003121	3636 ASPEN HEIGHTS PKWY APT 101	17-702-00-14-001.00-01	7/09/13	DISAPPROVED	DRB
	000 000	ERO 00 EROSION CONTROL	ERI0 0004 EROSION CONTROL			
		RES COMM: 1-Need lateral bracing at proper locations for roof trusses				
12	00003195	3621 ASPEN HEIGHTS PKWY	17-702-00-14-001.00-01	7/15/13	DISAPPROVED	DRB
	000 000	ERO 00 EROSION CONTROL	ERI0 0003 EROSION CONTROL			
		RES COMM: 1-Fireblock chase at 2nd floor				
		RES COMM: 2-Will need tempered windows at required locations, can				
		RES COMM: check at final				
12	00003199	3639 ASPEN HEIGHTS PKWY	17-702-00-14-001.00-01	7/31/13	DISAPPROVED	DSV
	000 000	ERO 00 EROSION CONTROL	ERI0 0006 EROSION CONTROL			
		RES COMM: not ready				
13	000020250	3100 BELINDA CT	ERI0 0006 EROSION CONTROL	7/22/13	DISAPPROVED	SCA
	000 000	ERO 00 EROSION CONTROL				
		RES COMM: 1. Clean street				
13	00001655	4415 CEDAR FALLS LN	16-104-00-02-144.00-01	7/03/13	DISAPPROVED	DRB
	000 000	ERO 00 EROSION CONTROL	ERI0 0005 EROSION CONTROL			

APPLICATION STRUCTR PERMIT PROPERTY ADDRESS
 County Parcel Number
 INSPECTION
 OLD Account Number
 RESULT DATE/STATUS
 INSPECTOR

13 00001655 CONTINUED
 RES COMM: 1-Driveway slope is not close, to be re-inspected by DRB

13 00001753 3804 TREFOIL DR
 000 000 ERO 00 EROSION CONTROL
 RES COMM: 1. Need silt fence at west side in areas where silt is
 RES COMM: moving to creek.

13 00001869 3908 WEATHERBY LN
 000 000 ERO 00 EROSION CONTROL
 RES COMM: 1. Repair/maintain silt fence, east side.
 RES COMM: 2. Extend silt fence 10-feet to southeast corner.
 RES COMM: 3. Clean mud/dirt/gravel from street.
 RES COMM: 4. Maintain 1-hour fire separation below platform of garage
 RES COMM: mech room.
 RES COMM: 5. Need nail-guard protection for wires located to right
 RES COMM: side of back patio door.

13 00001907 4203 EAGLE VIEW CT
 000 000 ERO 00 EROSION CONTROL
 RES COMM: 1. Install silt fence along rear of lot; silt protection
 RES COMM: especially needed at northeast corner of lot. 2nd notice.

13 00002221 6909 MONTAUK CT
 000 000 ERO 00 EROSION CONTROL
 RES COMM: 1. Furnace vent does not have adequate clearance from
 combustibles in attic.
 RES COMM: 2. Protect dryer vent with nail-guards, both sides.
 RES COMM: 3. Metal switch box at east hall has box fill violation.
 RES COMM: 4. Connect vent to east hall bath fan.
 RES COMM: 5. Install outlet box for ceiling fan at living room.
 RES COMM: 6. Clean dirt from street.

13 00002286 5901 NEPTUNE DR
 000 000 ERO 00 EROSION CONTROL
 RES COMM: 1-Need silt fence at rear of lot, no inspection

13 00002596 4611 COPPERSTONE CT
 000 000 ERO 00 EROSION CONTROL
 RES COMM: 1-Need silt fence at rear of lot, no inspection

13 00002790 4010 ABBINGTON TER
 000 000 ERO 00 EROSION CONTROL

APPLICATION STRUCTR PERMIT PROPERTY ADDRESS
County Parcel Number
INSPECTION

Old Account Number
RESULT DATE/STATUS
INSPECTOR

13 00002790 CONTINUED

RES COMM: 1-footing have not been dug

13 00002845 3402 GRAPE MYRTLE DR
000 000 ERO 00 EROSION CONTROL

16-803-00-04-006.00-01
ER10 0002 EROSION CONTROL
7/26/13 DISAPPROVED
RES COMM: 1-No inspections were performed, must resolve easement
RES COMM: issues before inspections can be done See Phil Teeple

DRB

13 00002856 3400 GRAPE MYRTLE DR
000 000 ERO 00 EROSION CONTROL

16-803-00-04-007.00-01
ER10 0002 EROSION CONTROL
7/26/13 DISAPPROVED
RES COMM: 1-No inspections were performed, must resolve easement
RES COMM: issues before inspections can be done See Phil Teeple

DRB