APPLICATION / STRUCTR	PROPERTY ADDRESS / PERMIT	County Parcel Number / INSPECTION	Old Account Number / RESULT DATE/STATUS	INSPECTOR
15 00002110	3110 CRAPE MYRTLE DR	16-803-00-04-051.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0005 EROSION CONTROL	2/05/16 DISAPPROVED	HHH
	RES COMM: need erosion control installed in back yard			
15 00002114	3200 CRAPE MYRTLE DR	16-803-00-04-052.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0005 EROSION CONTROL	2/05/16 DISAPPROVED	HHH
	RES COMM: need erosion control installed in back yard			
15 00002520	403 JOEY DR	- - - - . -		
000 000	ERO 00 EROSION CONTROL	ER10 0006 EROSION CONTROL	2/16/16 DISAPPROVED	DSV
	RES COMM: 1) need all sill bolts tightend			
	RES COMM: 2) need sill bolts at basement NW and SW corners			
	RES COMM: 3) need tempared windows			
	RES COMM: 4) need deck built (said they poured a footing when they			
	RES COMM: poared pad, told them to dig some up to verify)			
	RES COMM: 5) vent bath fans			
	RES COMM: 6) mark return bays, also at tub in SW bedroom, pan of			
	RES COMM: return at tub			
	RES COMM: 7) need light at stair well			
	RES COMM: 8) support pvc every 4' in attic			
15 00002681	3400 WISTERIA LN	- - - - . -		
000 000	ERO 00 EROSION CONTROL	ER10 0007 EROSION CONTROL	2/05/16 DISAPPROVED	HHH
15 00002682	3306 WISTERIA LN	16-803-00-04-081.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0007 EROSION CONTROL	2/05/16 DISAPPROVED	HHH
	RES COMM: need erosion control installed in back yard			
15 00002880	4600 SAWGRASS DR	16-700-00-00-003.02-01		
000 000	ERO 00 EROSION CONTROL	ER10 0004 EROSION CONTROL	2/25/16 DISAPPROVED	HHH
	RES COMM: clean silt basin out			
15 00002990	4307 PEREGRINE PL	- - - - . -		
000 000	ERO 00 EROSION CONTROL	ER10 0011 EROSION CONTROL	2/02/16 DISAPPROVED	HHH
	RES COMM: no erosion control in rear of home and erosion control on			
	RES COMM: downhill side needs to be repaired/replaced			
15 00003087	4108 STEINBROOKE TER	20-200-00-08-091.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0008 EROSION CONTROL	2/18/16 DISAPPROVED	HHH
	RES COMM: no erosion controlin rear of home			
15 00003173	3804 STEINBROOKE TER	20-200-00-08-111.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0005 EROSION CONTROL	2/18/16 DISAPPROVED	HHH
	RES COMM: no erosion controlin rear of home			

APPLICATION / STRUCTR	PERMIT	PROPERTY ADDRESS / County Parcel Number / Old Account Number / INSPECTION	RESULT DATE/STATUS	INSPECTOR
15 00003173	CONTINUED			
000 000	ERO 00 EROSION CONTROL	ER10 0006 EROSION CONTROL	2/19/16 DISAPPROVED	HHH
		RES COMM: need erosion control in rear yard		
15 00003209	4401 CANYATA CT	16-700-00-00-003.02-01		
000 000	ERO 00 EROSION CONTROL	ER10 0006 EROSION CONTROL	2/17/16 DISAPPROVED	HHH
		RES COMM: repair/ replace erosion control in rear of home		
16 00000123	1708 SWIFT CT	16-415-00-03-009.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0005 EROSION CONTROL	2/29/16 DISAPPROVED	HHH
		RES COMM: no erosion control in rear of home		
16 00000183	1513 WINDSOR ST APT 101	17-117-00-01-049.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0001 EROSION CONTROL	2/12/16 DISAPPROVED	SCA
		RES COMM: 1. Set backs are very close verify them at the GW		
		RES COMM: inspection. Informed DLK that lot was not the min. 60'		
		RES COMM: width. He said to pour them if it was like the plot plan.		
		RES COMM: So I did.		
16 00000184	1513 WINDSOR ST APT 102	17-117-00-01-049.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0001 EROSION CONTROL	2/12/16 DISAPPROVED	SCA
		RES COMM: 1. Set backs are very close verify them at the GW		
		RES COMM: inspection. Informed DLK that lot was not the min. 60'		
		RES COMM: width. He said to pour them if it was like the plot plan.		
		RES COMM: So I did.		
16 00000375	1712 GYPSY MOTH DR	17-105-00-02-025.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0005 EROSION CONTROL	2/10/16 DISAPPROVED	DRB
		RES COMM: permit put on hold, no inspection performed, need licensed		
		RES COMM: mechanic and business license		
16 00000514	4107 STEINBROOKE TER	20-200-00-08-127.02-01		
000 000	ERO 00 EROSION CONTROL	ER10 0007 EROSION CONTROL	2/24/16 DISAPPROVED	HHH
		RES COMM: repair silt along side yard		
16 00000568	2608 SUNFLOWER ST	16-207-00-11-001.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0001 EROSION CONTROL	2/01/16 DISAPPROVED	CAL
		RES COMM: 1. Install silt fence along north side, north stadium blvd		
16 00000590	4206 STEINBROOKE TER	20-200-00-08-087.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0004 EROSION CONTROL	2/19/16 DISAPPROVED	HHH
		RES COMM: install erosion control on southside of property		
000 000	ERO 00 EROSION CONTROL	ER10 0005 EROSION CONTROL	2/22/16 DISAPPROVED	HHH

APPLICATION / STRUCTR	PROPERTY ADDRESS / PERMIT	County Parcel Number / INSPECTION	Old Account Number / RESULT DATE/STATUS	INSPECTOR
16 00000590	CONTINUED			
		RES COMM: no erosion control on east side yard		
16 00000986	5504 STEEPLECHASE CT	20-100-00-02-102.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0002 EROSION CONTROL	2/16/16 DISAPPROVED	HHH
		RES COMM: no erosion control installed. eroding onto sidewalk and		
		RES COMM: onto Howard Orchard Rd below		
16 00001168	3400 TIMBER RUN DR	20-200-00-00-015.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0001 EROSION CONTROL	2/15/16 DISAPPROVED	DRB
		RES COMM: 1-not ready		
16 00001169	3502 TIMBER RUN DR	20-200-00-00-015.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0001 EROSION CONTROL	2/15/16 DISAPPROVED	DRB
		RES COMM: 1-not ready		

RPT TOTAL: 22

APPLICATION / STRUCTR	PROPERTY ADDRESS / PERMIT	County Parcel Number / INSPECTION	Old Account Number / RESULT DATE/STATUS	INSPECTOR
15 00002110	3110 CRAPE MYRTLE DR	16-803-00-04-051.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0005 EROSION CONTROL	2/05/16 DISAPPROVED	HHH
	RES COMM: need erosion control installed in back yard			
15 00002114	3200 CRAPE MYRTLE DR	16-803-00-04-052.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0005 EROSION CONTROL	2/05/16 DISAPPROVED	HHH
	RES COMM: need erosion control installed in back yard			
15 00002520	403 JOEY DR	- - - - . -		
000 000	ERO 00 EROSION CONTROL	ER10 0006 EROSION CONTROL	2/16/16 DISAPPROVED	DSV
	RES COMM: 1) need all sill bolts tightend			
	RES COMM: 2) need sill bolts at basement NW and SW corners			
	RES COMM: 3) need tempared windows			
	RES COMM: 4) need deck built (said they poured a footing when they			
	RES COMM: poared pad, told them to dig some up to verify)			
	RES COMM: 5) vent bath fans			
	RES COMM: 6) mark return bays, also at tub in SW bedroom, pan of			
	RES COMM: return at tub			
	RES COMM: 7) need light at stair well			
	RES COMM: 8) support pvc every 4' in attic			
15 00002681	3400 WISTERIA LN	- - - - . -		
000 000	ERO 00 EROSION CONTROL	ER10 0007 EROSION CONTROL	2/05/16 DISAPPROVED	HHH
15 00002682	3306 WISTERIA LN	16-803-00-04-081.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0007 EROSION CONTROL	2/05/16 DISAPPROVED	HHH
	RES COMM: need erosion control installed in back yard			
15 00002880	4600 SAWGRASS DR	16-700-00-00-003.02-01		
000 000	ERO 00 EROSION CONTROL	ER10 0004 EROSION CONTROL	2/25/16 DISAPPROVED	HHH
	RES COMM: clean silt basin out			
15 00002990	4307 PEREGRINE PL	- - - - . -		
000 000	ERO 00 EROSION CONTROL	ER10 0011 EROSION CONTROL	2/02/16 DISAPPROVED	HHH
	RES COMM: no erosion control in rear of home and erosion control on			
	RES COMM: downhill side needs to be repaired/replaced			
15 00003087	4108 STEINBROOKE TER	20-200-00-08-091.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0008 EROSION CONTROL	2/18/16 DISAPPROVED	HHH
	RES COMM: no erosion controlin rear of home			
15 00003173	3804 STEINBROOKE TER	20-200-00-08-111.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0005 EROSION CONTROL	2/18/16 DISAPPROVED	HHH
	RES COMM: no erosion controlin rear of home			

APPLICATION / STRUCTR	PROPERTY ADDRESS / PERMIT	County Parcel Number / INSPECTION	Old Account Number / RESULT DATE/STATUS	INSPECTOR
15 00003173	CONTINUED			
000 000	ERO 00 EROSION CONTROL	ER10 0006 EROSION CONTROL	2/19/16 DISAPPROVED	HHH
	RES COMM: need erosion control in rear yard			
15 00003209	4401 CANYATA CT	16-700-00-00-003.02-01		
000 000	ERO 00 EROSION CONTROL	ER10 0006 EROSION CONTROL	2/17/16 DISAPPROVED	HHH
	RES COMM: repair/ replace erosion control in rear of home			
16 00000123	1708 SWIFT CT	16-415-00-03-009.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0005 EROSION CONTROL	2/29/16 DISAPPROVED	HHH
	RES COMM: no erosion control in rear of home			
16 00000183	1513 WINDSOR ST APT 101	17-117-00-01-049.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0001 EROSION CONTROL	2/12/16 DISAPPROVED	SCA
	RES COMM: 1. Set backs are very close verify them at the GW			
	RES COMM: inspection. Informed DLK that lot was not the min. 60'			
	RES COMM: width. He said to pour them if it was like the plot plan.			
	RES COMM: So I did.			
16 00000184	1513 WINDSOR ST APT 102	17-117-00-01-049.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0001 EROSION CONTROL	2/12/16 DISAPPROVED	SCA
	RES COMM: 1. Set backs are very close verify them at the GW			
	RES COMM: inspection. Informed DLK that lot was not the min. 60'			
	RES COMM: width. He said to pour them if it was like the plot plan.			
	RES COMM: So I did.			
16 00000375	1712 GYPSY MOTH DR	17-105-00-02-025.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0005 EROSION CONTROL	2/10/16 DISAPPROVED	DRB
	RES COMM: permit put on hold, no inspection performed, need licensed			
	RES COMM: mechanic and business license			
16 00000514	4107 STEINBROOKE TER	20-200-00-08-127.02-01		
000 000	ERO 00 EROSION CONTROL	ER10 0007 EROSION CONTROL	2/24/16 DISAPPROVED	HHH
	RES COMM: repair silt along side yard			
16 00000568	2608 SUNFLOWER ST	16-207-00-11-001.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0001 EROSION CONTROL	2/01/16 DISAPPROVED	CAL
	RES COMM: 1. Install silt fence along north side, north stadium blvd			
16 00000590	4206 STEINBROOKE TER	20-200-00-08-087.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0004 EROSION CONTROL	2/19/16 DISAPPROVED	HHH
	RES COMM: install erosion control on southside of property			
000 000	ERO 00 EROSION CONTROL	ER10 0005 EROSION CONTROL	2/22/16 DISAPPROVED	HHH

APPLICATION / STRUCTR / PERMIT	PROPERTY ADDRESS	County Parcel Number / INSPECTION	Old Account Number / RESULT DATE/STATUS	INSPECTOR
16 00000590	CONTINUED			
		RES COMM: no erosion control on east side yard		
16 00000986	5504 STEEPLECHASE CT	20-100-00-02-102.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0002 EROSION CONTROL	2/16/16 DISAPPROVED	HHH
		RES COMM: no erosion control installed. eroding onto sidewalk and		
		RES COMM: onto Howard Orchard Rd below		
16 00001168	3400 TIMBER RUN DR	20-200-00-00-015.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0001 EROSION CONTROL	2/15/16 DISAPPROVED	DRB
		RES COMM: 1-not ready		
16 00001169	3502 TIMBER RUN DR	20-200-00-00-015.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0001 EROSION CONTROL	2/15/16 DISAPPROVED	DRB
		RES COMM: 1-not ready		

RPT TOTAL: 22

APPLICATION / STRUCTR	PROPERTY ADDRESS / PERMIT	County Parcel Number / INSPECTION	Old Account Number / RESULT DATE/STATUS	INSPECTOR
15 00002110	3110 CRAPE MYRTLE DR	16-803-00-04-051.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0005 EROSION CONTROL	2/05/16 DISAPPROVED	HHH
	RES COMM: need erosion control installed in back yard			
15 00002114	3200 CRAPE MYRTLE DR	16-803-00-04-052.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0005 EROSION CONTROL	2/05/16 DISAPPROVED	HHH
	RES COMM: need erosion control installed in back yard			
15 00002520	403 JOEY DR	- - - - . -		
000 000	ERO 00 EROSION CONTROL	ER10 0006 EROSION CONTROL	2/16/16 DISAPPROVED	DSV
	RES COMM: 1) need all sill bolts tightend			
	RES COMM: 2) need sill bolts at basement NW and SW corners			
	RES COMM: 3) need tempared windows			
	RES COMM: 4) need deck built (said they poured a footing when they			
	RES COMM: poared pad, told them to dig some up to verify)			
	RES COMM: 5) vent bath fans			
	RES COMM: 6) mark return bays, also at tub in SW bedroom, pan of			
	RES COMM: return at tub			
	RES COMM: 7) need light at stair well			
	RES COMM: 8) support pvc every 4' in attic			
15 00002681	3400 WISTERIA LN	- - - - . -		
000 000	ERO 00 EROSION CONTROL	ER10 0007 EROSION CONTROL	2/05/16 DISAPPROVED	HHH
15 00002682	3306 WISTERIA LN	16-803-00-04-081.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0007 EROSION CONTROL	2/05/16 DISAPPROVED	HHH
	RES COMM: need erosion control installed in back yard			
15 00002880	4600 SAWGRASS DR	16-700-00-00-003.02-01		
000 000	ERO 00 EROSION CONTROL	ER10 0004 EROSION CONTROL	2/25/16 DISAPPROVED	HHH
	RES COMM: clean silt basin out			
15 00002990	4307 PEREGRINE PL	- - - - . -		
000 000	ERO 00 EROSION CONTROL	ER10 0011 EROSION CONTROL	2/02/16 DISAPPROVED	HHH
	RES COMM: no erosion control in rear of home and erosion control on			
	RES COMM: downhill side needs to be repaired/replaced			
15 00003087	4108 STEINBROOKE TER	20-200-00-08-091.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0008 EROSION CONTROL	2/18/16 DISAPPROVED	HHH
	RES COMM: no erosion controlin rear of home			
15 00003173	3804 STEINBROOKE TER	20-200-00-08-111.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0005 EROSION CONTROL	2/18/16 DISAPPROVED	HHH
	RES COMM: no erosion controlin rear of home			

APPLICATION / STRUCTR / PERMIT	PROPERTY ADDRESS	County Parcel Number / INSPECTION	Old Account Number / RESULT DATE/STATUS	INSPECTOR
15 00003173	CONTINUED			
000 000	ERO 00 EROSION CONTROL	ER10 0006 EROSION CONTROL	2/19/16 DISAPPROVED	HHH
	RES COMM: need erosion control in rear yard			
15 00003209	4401 CANYATA CT	16-700-00-00-003.02-01		
000 000	ERO 00 EROSION CONTROL	ER10 0006 EROSION CONTROL	2/17/16 DISAPPROVED	HHH
	RES COMM: repair/ replace erosion control in rear of home			
16 00000123	1708 SWIFT CT	16-415-00-03-009.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0005 EROSION CONTROL	2/29/16 DISAPPROVED	HHH
	RES COMM: no erosion control in rear of home			
16 00000183	1513 WINDSOR ST APT 101	17-117-00-01-049.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0001 EROSION CONTROL	2/12/16 DISAPPROVED	SCA
	RES COMM: 1. Set backs are very close verify them at the GW			
	RES COMM: inspection. Informed DLK that lot was not the min. 60'			
	RES COMM: width. He said to pour them if it was like the plot plan.			
	RES COMM: So I did.			
16 00000184	1513 WINDSOR ST APT 102	17-117-00-01-049.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0001 EROSION CONTROL	2/12/16 DISAPPROVED	SCA
	RES COMM: 1. Set backs are very close verify them at the GW			
	RES COMM: inspection. Informed DLK that lot was not the min. 60'			
	RES COMM: width. He said to pour them if it was like the plot plan.			
	RES COMM: So I did.			
16 00000375	1712 GYPSY MOTH DR	17-105-00-02-025.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0005 EROSION CONTROL	2/10/16 DISAPPROVED	DRB
	RES COMM: permit put on hold, no inspection performed, need licensed			
	RES COMM: mechanic and business license			
16 00000514	4107 STEINBROOKE TER	20-200-00-08-127.02-01		
000 000	ERO 00 EROSION CONTROL	ER10 0007 EROSION CONTROL	2/24/16 DISAPPROVED	HHH
	RES COMM: repair silt along side yard			
16 00000568	2608 SUNFLOWER ST	16-207-00-11-001.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0001 EROSION CONTROL	2/01/16 DISAPPROVED	CAL
	RES COMM: 1. Install silt fence along north side, north stadium blvd			
16 00000590	4206 STEINBROOKE TER	20-200-00-08-087.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0004 EROSION CONTROL	2/19/16 DISAPPROVED	HHH
	RES COMM: install erosion control on southside of property			
000 000	ERO 00 EROSION CONTROL	ER10 0005 EROSION CONTROL	2/22/16 DISAPPROVED	HHH

APPLICATION STRUCTR	PROPERTY ADDRESS PERMIT	County Parcel Number INSPECTION	Old Account Number RESULT DATE/STATUS	INSPECTOR
16 00000590	CONTINUED			
		RES COMM: no erosion control on east side yard		
16 00000986	5504 STEEPLECHASE CT	20-100-00-02-102.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0002 EROSION CONTROL	2/16/16 DISAPPROVED	HHH
		RES COMM: no erosion control installed. eroding onto sidewalk and		
		RES COMM: onto Howard Orchard Rd below		
16 00001168	3400 TIMBER RUN DR	20-200-00-00-015.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0001 EROSION CONTROL	2/15/16 DISAPPROVED	DRB
		RES COMM: 1-not ready		
16 00001169	3502 TIMBER RUN DR	20-200-00-00-015.00-01		
000 000	ERO 00 EROSION CONTROL	ER10 0001 EROSION CONTROL	2/15/16 DISAPPROVED	DRB
		RES COMM: 1-not ready		

RPT TOTAL: 22