

Facility: MKT Trail Recreation Area

Address: 3662 Scott Blvd.

Date of Survey: 05/25/10



1 ACCESS TO THE SITE AND/OR FACILITY

1.1 Exterior Accessible Route (sidewalks, paths, etc.)

- Refer to site plan included with this report: (A) Install ~ 126 l.f. of new 4' wide concrete or asphalt access path from the existing sidewalk east of the restroom building (see photo 1 below) over to the existing paved trail access point west of the restroom building (see photo 2 below). **Estimated Cost: \$3,403.00**



Photo 1



Photo 2

- Refer to site plan included with this report: (B) Install ~ 72 l.f. of new 4' wide concrete or asphalt access path from new access path over to the parking lot near the accessible parking spaces (see photo 3 below).

Estimated Cost: \$2,150.00



Photo 3

1.2 Parking

- Refer to site plan included with this report: (C) Parking lot has 28 total parking spaces. Therefore, ADAAG requires 2 accessible parking spaces. Add one space at location of existing ADA parking space (min. 8' wide space on south side of the existing ADA parking access aisle and add a sign mounted at 72" above grade.

Estimated Cost: \$243.00

1.3 Curb Cuts & Curb Ramps

- Refer to site plan included with this report: (D) Saw-cut and remove a min. 36" wide section of existing curb near soccer field seating area to allow access to new concrete wheelchair seating pad to be installed (see Section 2.9).

Estimated Cost: \$200.00

1.4 Exterior Ramps

- None exist.

1.5 Exterior Stairs

- None exist.

2 SERVICES

2.1 Building Entrances (exterior doors)

- Not applicable.

2.2 Interior Accessible Route

- Not applicable.

2.3 Interior Ramps

- Not applicable.

2.4 Interior Stairs

- Not applicable.

2.5 Elevators

- Not applicable.

2.6 Platform (wheelchair) Lifts

- None exist.

2.7 Doors (interior, excluding restroom doors addressed in 3.1 and non-public area doors)

- Not applicable.

2.8 Places of Assembly (auditoriums, meeting rooms, gymnasiums, etc.)

- Not applicable.

2.9 Seating and Tables

- Install a min. 4'x6' concrete pad adjacent to fixed bench at the soccer field (see photo 4 next page). **Estimated Cost: \$612.00**



Photo 4

2.10 Restaurant (including dining areas, snack bars & public use kitchens)

- Not applicable.

2.11 NOT USED

2.12 Business and Mercantile

- Not applicable.

2.13 Dressing and Fitting Rooms

- Not applicable.

2.14 NOT USED

2.15 NOT USED

2.16 Libraries

- Not applicable.

2.17 Storage

- Not applicable.

3 ACCESS TO PUBLIC AMENITIES

3.1 Drinking Fountains

- No work.

3.2 Restrooms

- No work.

3.3 Signage

- Not applicable.

3.4 Bathtub & Showers (including locker rooms and dressing rooms)

- Not applicable.

4 BARRIER REMOVAL - OTHER

4.1 Alarms

- Not applicable.

4.2 Public Telephones

- None exist.

4.3 Protruding Objects

- None exist.

4.4 Playgrounds

- None exist.

4.5 Sinks, Other than Lavatories

- Not applicable.

5 COST ESTIMATE

5.1 Cost Estimate & Notes

- Total facility cost estimate for recommended ADA modifications: **\$6,608.00**

FACILITY SUMMARY		NAME: MKT TRAIL ACCESS & RESTROOMS
SECTION HEADING	COST	COMMENTS

1 Access to the Facility

1.1 Exterior Accessible Route	5,553.00	Add access paths to RR & trail access
1.2 Parking	243.00	Add sign & marking for new parking space
1.3 Curb Ramps	200.00	Cut section of curb out for access to soccer field.
1.4 Exterior Ramps	-	
1.5 Exterior Stairs	-	

2 Services

2.1 Building Entrances	-	
2.2 Interior Accessible Route	-	
2.3 Interior Ramps	-	
2.4 Interior Stairs	-	
2.5 Elevators	-	
2.6 Platform Lifts	-	
2.7 Doors	-	
2.8 Places of Assembly	-	
2.9 Seating and Tables	612.00	Install wheelchair seating pad @ soccer field
2.10 Restaurant	-	
2.11 NOT USED	-	
2.12 Business and Mercantile	-	
2.13 Dressing and Fitting Rooms	-	
2.14 NOT USED	-	
2.15 NOT USED	-	
2.16 Libraries	-	
2.17 Storage	-	

3 Access to Public Amenities

3.1 Drinking Fountains	-	
3.2 Toilet Rooms	-	
3.3 Signage	-	
3.4 Bathtubs and Showers	-	

4 Barrier Removal - Other

4.1 Alarms	-	
4.2 Public Telephones	-	
4.3 Protruding Objects	-	
4.4 Work Areas	-	
4.5 Sinks, Other than Lavatories	-	

Total Barrier Removal Cost	6,608.00	
-----------------------------------	----------	--



This Page Intentionally Left Blank