
 APPLICATION STRUCTR PERMIT
 PROPERTY ADDRESS
 County Parcel Number
 INSPECTION
 Old Account Number
 RESULT DATE/STATUS
 INSPECTOR

12 00003051 3732 ASPEN HEIGHTS PKWY 17-702-00-14-001.00-01 8/05/13 DISAPPROVED DRB
 000 000 ERO 00 EROSION CONTROL ERI0 0002 EROSION CONTROL
 RES COMM: 1-Not ready for inspection

12 00003161 3728 ASPEN HEIGHTS PKWY APT 100 17-702-00-14-001.00-01 8/05/13 DISAPPROVED DRB
 000 000 ERO 00 EROSION CONTROL ERI0 0002 EROSION CONTROL
 RES COMM: 1-Not ready for inspection

12 00003162 3728 ASPEN HEIGHTS PKWY APT 101 17-702-00-14-001.00-01 8/05/13 DISAPPROVED DRB
 000 000 ERO 00 EROSION CONTROL ERI0 0002 EROSION CONTROL
 RES COMM: 1-Not ready for inspection

12 00003212 3730 ASPEN HEIGHTS PKWY 17-702-00-14-001.00-01 8/05/13 DISAPPROVED DRB
 000 000 ERO 00 EROSION CONTROL ERI0 0003 EROSION CONTROL
 RES COMM: 1-Not ready for inspection

13 00001287 1805 PRIMUS DR 17-202-00-03-156.00-01 8/20/13 DISAPPROVED CAL
 000 000 ERO 00 EROSION CONTROL ERI0 0008 EROSION CONTROL
 RES COMM: 1. Post address in permanent fashion.
 RES COMM: 2. Need locking caps at outdoor AC unit.
 RES COMM: 3. Grade/repair disturbed earth at sewer easement.
 RES COMM: 4. Install erosion control at silt runoff into drainage
 RES COMM: ditch.

13 00001635 2109 DOMAIN HILL CT 17-504-00-01-110.00-01 8/06/13 DISAPPROVED SCA
 000 000 ERO 00 EROSION CONTROL ERI0 0006 EROSION CONTROL
 RES COMM: Complain inspection: Install fence at west lot line. ASAP.
 RES COMM: Was preparing to sod when rain occurred in his defense.

13 00001794 2500 SPANISH BAY DR 17-504-00-01-110.00-01 8/08/13 DISAPPROVED SCA
 000 000 ERO 00 EROSION CONTROL ERI0 0006 EROSION CONTROL
 RES COMM: Work incomplete

13 00001821 6504 GOLD FINCH CT 17-600-00-01-215.00-01 8/01/13 DISAPPROVED DRB
 000 000 ERO 00 EROSION CONTROL ERI0 0006 EROSION CONTROL
 RES COMM: 1-Drive approach not formed

13 00001863 6902 MONTAUK CT 20-200-00-00-019.00-01 8/14/13 DISAPPROVED CAL
 000 000 ERO 00 EROSION CONTROL ERI0 0003 EROSION CONTROL
 RES COMM: 1. Install silt fence at rear
 RES COMM: 2
 RES COMM: Need insulation shield around water heater vent in attic 3.

13 00001869 3908 WEATHERBY LN 17-501-00-01-046.00-01 8/29/13 DISAPPROVED DRB
 000 000 ERO 00 EROSION CONTROL ERI0 0007 EROSION CONTROL

APPLICATION PERMIT PROPERTY ADDRESS
STRUCTR PERMIT

County Parcel Number
INSPECTION

Old Account Number
RESULT DATE/STATUS
INSPECTOR

13 00001869 CONTINUED

RES COMM: Repair silt fence on east side of lot, contractor notified

13 00002411 607 RHINO CT
000 000 ERO 00 EROSION CONTROL
RES COMM: 1. Install silt fence all along rear property line.

11-903-00-01-077.00-01
ER10 0006 EROSION CONTROL

8/08/13 DISAPPROVED

CAL

13 00002535 4404 RYEFIELD CT
000 000 ERO 00 EROSION CONTROL
RES COMM: 1-Need silt fence protecting creek at rear

16-104-00-00-006.00-01
ER10 0002 EROSION CONTROL

8/13/13 DISAPPROVED

DRB

REQ COMM: Erosion control needed to prevent sediment running into the creek. Needs to be corrected as soon as possible.
REQ COMM: T/S: 07/19/2013 02:14 PM DMHAGENH --
RES COMM: 1-Need silt fence protecting creek at rear

13 00002571 6802 MONTAUK CT
000 000 ERO 00 EROSION CONTROL
RES COMM: 1. Silt running into drainage ditch located at middle rear
RES COMM: of lot. Install silt fence to control run-off.

20-200-00-00-019.00-01
ER10 0002 EROSION CONTROL

8/16/13 DISAPPROVED

CAL

13 00002634 1204 RAINBOW TROUT CIR
000 000 ERO 00 EROSION CONTROL
RES COMM: 1. Install silt fence at rear of lot.
RES COMM: 2. Protect storm drain inlet at rear of lot.

ER10 0002 EROSION CONTROL

8/02/13 DISAPPROVED

CAL

13 00002637 1208 RAINBOW TROUT CIR
000 000 ERO 00 EROSION CONTROL
RES COMM: 1. Install silt fence at rear of lot.
RES COMM: 2. Protect storm drain inlet at rear of lot.

ER10 0002 EROSION CONTROL

8/02/13 DISAPPROVED

CAL

13 00002987 6311 UPPER BRIDLE BEND DR
000 000 ERO 00 EROSION CONTROL
RES COMM: 1-Not ready for inspection

17-600-00-01-036.00-01
ER10 0001 EROSION CONTROL

8/09/13 DISAPPROVED

DRB