

| APPLICATION STRUCTR | PROPERTY ADDRESS PERMIT | County Parcel Number INSPECTION | Old Account Number RESULT DATE/STATUS | INSPECTOR |
|------------------------|---|---|--|-----------|
| 16 00000664 000 000 | 3500 SCOTT BLVD BLDG 15 ERO 00 EROSION CONTROL | 16-801-00-15-030.00-01 ER10 0006 EROSION CONTROL | 10/28/16 DISAPPROVED | CKF |
| | | RES COMM: 1 Label meter bases. RES COMM: 2 insulate conduit into panel to prevent condensation into RES COMM: both panels | | |
| 16 00001260 000.000 | 5303 PERCHE POINTE PL ERO 00 EROSION CONTROL | 16-415-00-01-056.00-01 ER10 0011 EROSION CONTROL | 10/07/16 DISAPPROVED | HHH |
| | | RES COMM: need erosion control in rear low point of yard to the NW | | |
| 16 00001561 000 000 | 4604 VILLA WOOD CT ERO 00 EROSION CONTROL | 20-100-00-01-261.00-01 ER10 0008 EROSION CONTROL | 10/10/16 DISAPPROVED | HHH |
| | | RES COMM: no erosion control rear of home, clean mud and silt from RES COMM: MODOT right way and recut ditch to proper grade | | |
| 16 00001991 000 000 | 309 PERCHE RIDGE DR ERO 00 EROSION CONTROL | 16-104-00-02-203.00-01 ER10 0006 EROSION CONTROL | 10/31/16 DISAPPROVED | HHH |
| | | RES COMM: install erosion control in rear of home | | |
| 16 00002054 000 000 | 4110 HURON CT ERO 00 EROSION CONTROL | 20-200-00-09-033.00-01 ER10 0011 EROSION CONTROL | 10/18/16 DISAPPROVED | HHH |
| | | RES COMM: no erosion control installed in low point | | |
| 16 00002154 000 000 | 808 ENGLE DR ERO 00 EROSION CONTROL | 20-306-00-05-039.00-01 ER10 0005 EROSION CONTROL | 10/04/16 DISAPPROVED | HHH |
| | | RES COMM: no erosion control installed, freshly graded yard | | |
| 16 00002372 000 000 | 4808 MCMICKLE DR ERO 00 EROSION CONTROL | 16-104-00-02-197.00-01 ER10 0006 EROSION CONTROL | 10/31/16 DISAPPROVED | HHH |
| | | RES COMM: install erosion control in rear swale | | |
| 16 00002504 000 000 | 2104 NOTTOWAY DR ERO 00 EROSION CONTROL | 20-200-00-06-136.00-01 ER10 0003 EROSION CONTROL | 10/28/16 DISAPPROVED | HHH |
| 16 00002594 000 000 | 811 ENGLE DR ERO 00 EROSION CONTROL | 20-306-00-05-075.00-01 ER10 0006 EROSION CONTROL | 10/10/16 DISAPPROVED | HHH |
| | | RES COMM: repair erosion control on dow hill side front | | |
| 16 00003121 000 000 | 6802 SCOTT BLVD ERO 00 EROSION CONTROL | 20-200-00-09-032.00-01 ER10 0001 EROSION CONTROL | 10/20/16 DISAPPROVED | CAL |
| | | RES COMM: 1. Install silt fence at front left area of lot. | | |
| 16 00003190 000 000 | 5405 STEEPLECHASE DR ERO 00 EROSION CONTROL | 20-100-00-02-105.00-01 ER10 0001 EROSION CONTROL | 10/27/16 DISAPPROVED | SCA |

| APPLICATION STRUCTR | PROPERTY ADDRESS PERMIT | County Parcel Number INSPECTION | Old Account Number RESULT DATE/STATUS | INSPECTOR |
|------------------------|----------------------------|---|--|-----------|
| 16 00003190 | CONTINUED | | | |
| | | RES COMM: 1. Not ready | | |
| 000 000 | ERO 00 EROSION CONTROL | ER10 0002 EROSION CONTROL | 10/28/16 DISAPPROVED | DSV |
| | | RES COMM: no plot plan on site, Mark fenton job needs to have foam in | | |
| | | RES COMM: footing before approval | | |
| 16 00003283 | 4309 CHANCELLOR CIR | 11-902-00-01-084.00-01 | | |
| 000 000 | ERO 00 EROSION CONTROL | ER10 0002 EROSION CONTROL | 10/19/16 DISAPPROVED | CAL |
| | | RES COMM: 1. No permit on site. | | |

RPT TOTAL: 13