

APPLICATION PROPERTY ADDRESS
STRUCTR PERMIT

County Parcel Number
INSPECTION

Old Account Number
RESULT DATE/STATUS

INSPECTOR

13 00002940 6512 CASHS CROSSING
000 000 ERO 00 EROSION CONTROL

RES COMM: 1- sidewalk not ready

17-600-00-01-236.00-01
ER10 0009 EROSION CONTROL

2/19/14 DISAPPROVED
DRB

13 00003457 1001 WESTPORT DR
000 000 ERO 00 EROSION CONTROL

RES COMM: 1. repair silt fence along front of lot.
RES COMM: 2. Install silt fence south side of lot.

16-510-00-01-018.00-01
ER10 0004 EROSION CONTROL

2/20/14 DISAPPROVED
CAL

13 00003643 5309 TITTREE CT
000 000 ERO 00 EROSION CONTROL

RES COMM: 1. Repair and extend silt fence northwest corner area.
RES COMM: 2. Both dryer vents are incomplete.
RES COMM: 3. Chimney vent incomplete.
RES COMM: 4. Furnace is not vented; no gas tag.
RES COMM: 5. Seal return air headers at basement southeast bed and
RES COMM: under stairs.
RES COMM: 6. Fireblock top of doubled walls, concealed spaces,
RES COMM: soffits and lowered ceilings.
RES COMM: 7. Supply duct is incomplete above basement bathroom.
RES COMM: 8. Deck is not ready; cantilevered floor joists may need
RES COMM: bearing support.
RES COMM: 9. Framing incomplete at B-vent in closet main floor.
RES COMM: 10. Ground metal receptacle box at pantry area.
RES COMM: 11. Provide lateral support for ceiling joists above
RES COMM: entryway.

16-419-00-04-020.00-01
ER10 0004 EROSION CONTROL

2/21/14 DISAPPROVED
CAL

13 00003978 5602 NEARPOINT CT
000 000 ERO 00 EROSION CONTROL

RES COMM: 1. FURNACE MUST BE VENTED FOR GAS TAG. 2. NO PRESSURE ON
RES COMM: GAS LINE.

20-200-00-08-064.00-01
ER10 0005 EROSION CONTROL

2/10/14 DISAPPROVED
SCA