
 APPLICATION STRUCTR PERMIT PROPERTY ADDRESS County Parcel Number Old Account Number
 INSPECTION INSPECTION RESULT DATE/STATUS INSPECTOR

13 00003659 401 BURNING BUSH RD 11-908-00-02-027.00-01 2/10/15 DISAPPROVED DMH
 ERO 00 EROSION CONTROL RES COMM: Back yard in an erosive surface, sediment discharge to the
 RES COMM: west of property.

13 00003909 1708 MILLS DR 16-516-00-12-027.00-01 2/27/15 DISAPPROVED CAL
 ERO 00 EROSION CONTROL RES COMM: ERI0 0004 EROSION CONTROL
 RES COMM: 1. Protect storm drain at front yard from silt
 RES COMM: Infiltration.

14 00001696 1300 GLASGOW DR 20-309-00-01-019.00-01 2/03/15 DISAPPROVED HHH
 ERO 00 EROSION CONTROL RES COMM: ERI0 0007 EROSION CONTROL
 RES COMM: no silt fence along downhill side of lot or East side

14 00002762 5700 SAULTON CT 20-100-00-02-060.00-01 2/24/15 DISAPPROVED HHH
 ERO 00 EROSION CONTROL RES COMM: ERI0 0008 EROSION CONTROL
 RES COMM: no erosion control installed down the hill

14 00002947 797 CUTTERS CORNER LN 17-600-00-01-001.00-01 2/20/15 DISAPPROVED DSV
 ERO 00 EROSION CONTROL RES COMM: ERI0 0003 EROSION CONTROL
 RES COMM: not ready for inspection, trades were still working

15 00000149 4600 COPPERSTONE CT 16-803-00-02-015.00-01 2/25/15 DISAPPROVED SCA
 ERO 00 EROSION CONTROL RES COMM: ERI0 0003 EROSION CONTROL
 RES COMM: 1. Defleccences exist, see framing notes.

RPT TOTAL: 6